

NAVAL STATION MAYPORT MAYPORT, FLORIDA BHATE PROJECT NO: 9970082 FL-COMPQAP NO: 970052

ADDENDUM TO THE CONTAMINATION ASSESSMENT REPORT NSC FUEL FARM

Prepared for:

DEPARTMENT OF THE NAVY
SOUTHERN DIVISION
NAVAL FACILITIES ENGINEERING COMMAND
2155 EAGLE DRIVE, POST OFFICE BOX 190010
NORTH CHARLESTON, SOUTH CAROLINA 29419-1910

Prepared by:

BHATE ENVIRONMENTAL ASSOCIATES, INC. 1608 13th AVENUE SOUTH BIRMINGHAM, ALABAMA 35205 TELEPHONE: (205) 918-4000

Bhate Environmental Associates, Inc. Environmental Engineers & Scientists

STATEMENT OF WORK

1.0 GENERAL INTENTION

- 1.1 SCOPE. The contractor shall provide all labor, equipment and materials, required to perform remedial activities at the Naval Supply Center (NSC) Fuel Farm at Mayport Naval Station, Mayport, Florida.
- 1.2 GENERAL DESCRIPTION. The work includes the requirements specified in the Environmental Response Action Contract N62467-98-D-0995, the Detailed Requirements, and work necessary to remediate the site in accordance with Florida Administrative Codes 62-761 and 62-770. The following phases may be required:
 - a. Phase 1 Information gathering/remedial technology selection
 - b. Phase 2 Strategic Planning meetings and site visits to include all required submittals, Remedial Action Plan, and project budget estimate
 - c. Phase 3 Specified site remediation
 - d. Phase 4 Project Closeout reporting
 - e. Phase 5 Long Term Monitoring

Additional phases and tasks beyond those identified in the original delivery order and subsequent modifications, will be negotiated and included at a later date by formal modification to this delivery order.

- 1.2.1 LOCATION. The work is located at the NSC Fuel Farm, Naval Station Mayport, Florida.
- 1.2.2 <u>DESCRIPTION OF CONTAMINANTS PRESENT.</u> There is petroleum-contaminated soil and groundwater and possibly free product at this site.

2.0 APPLICABLE DOCUMENTS

- 2.1 <u>REFERENCE REPORTS ACCOMPANYING SPECIFICATION.</u> The following reference reports accompany this statement of work and are intended to act as design guidance for the remedial activities at the site. These specifications are property of the Government and shall not be used for any purpose other than that intended by the specification.
 - 1. Contamination Assessment Report NSC Fuel Farm, Dtd. December 10, 1997, Bhate Environmental Associates, Inc.
 - 2. Addendum to the Contamination Assessment Report, Dtd. September 29, 1998, Bhate Environmental Associates, Inc.
 - 3. Replace Fuel Tanks, Naval Station Mayport, 90% Design submittal, Dtd. Oct., 1998, Enterprise Engineering, Inc. (Subject to update to final document)
 - 4. Guidance for Construction Completion Reports For RAC Contracts

3.0 GENERAL REQUIREMENTS

3.1 FACILITIES AND SERVICES

3.1.1 Availability of Utilities Services. The availability, type, and possible cost of any utility services provided to the contractor will be determined during phase 2. The basis for this determination will be the type of utilities available at the site, the amount of the services required, and the cost of the services.

3.2 SUBMITTALS FROM BASIC CONTRACT

3.2.1 <u>Submittal Delivery Schedule.</u> Government will establish the time frames for each of the required submittals for this delivery order during discussions with contractor.

4.0 DETAILED REQUIREMENTS

- 4.1 TASK. Remediation Activities at NSC Fuel Farm, Mayport Naval Station, Mayport, Fl.
- 4.1.1 Phase 1. The contractor will contact Beverly Washington, at (843)820-5581 to determine the current status of site studies and to gain access to all additional relevant information concerning site remediation. The contractor shall, if necessary, conduct a site visit and consult with study contractor, Military Construction design contractor and Navy personnel to obtain all necessary background information available to prepare the documents required under phase 2 of the project.
- 4.1.2 Phase 2. The contractor will develop a Remedial Action Plan (RAP) for the site in accordance with Florida Administrative Code 62-770 and upon Navy review and approval, submit it to the Florida Department of Environmental Protection(FDEP) for approval. The contractor shall then develop project budget submittals based on the FDEP approved RAP, data collected, the information contained in the reference reports, and decisions reached during the technical discussions. This and all other required documentation shall be submitted to the Government for review and approval.
- 4.1.3 Phase 3. After phase 2 is completed and acceptable, the Government will notify the contractor so that he can begin the remediation. The contractor will perform the work in accordance with the plans and submittals approved in phase 2 and the requirements listed in the Environmental Response Action Contract N62467-98-D-0995.
- 4.1.4 Phase 4. After completion of the project, the contractor shall prepare and submit a closeout report for the site in accordance with ref. document 4.

5.0 SCHEDULE OF PERFORMANCE

5.1 <u>COMMENCEMENT, PROSECUTION, AND COMPLETION OF WORK.</u> The contractor shall be required to commence work under this delivery order, prosecute the work diligently, and complete the entire project in the manner and time agreed to in the approved Phase 2 meetings, Remedial Action Plan and submittals.

Ralph Crist FISC Fuel Depot 8808 Somers Rd Jacksonville, FL 32218-2600

Concerns of NSC Fuel Farm

1. Contaminated Soil Zones:

Enterprise Engineering will excavate soils in Zone C (as specified in Bhate's July 15, 1998 letter) only. Zone C represents soil depths at elevations of 10 to 15 feet above Mean Sea Level (msl). Soils in this zone are estimated to be 468 cubic yards.

The approximate disposal cost is --- $468 \text{ cu. yds } \times \$75.00 / \text{ cu. yds} = \$35,000.00.$ (I believe this cost is before contractor mark-up).

A unit cost for additional contaminated soil removal and disposal will be in the specs.

2. Untouched Soil Zones:

The existing foundation for tank 202 will remain in place. The foundation is at an elevation of 10 feet above msl. Enterprise's Engineering designs show no excavation occurring in zones A and B. Zone A represents soil depths at elevations 2 to 5 feet above msl. Zone B represents soil depths at elevations 5 to 10 above msl.

Soil contaminated in Zones A and B are estimated at 4,333 cu. yds. and 1684 cu. yds. respectively.

3. Soil Contamination Directly Beneath Tank 202:

Soil contamination may exist directly beneath the concrete foundation. Borings will be taken at the center of and at equally spaced intervals of the existing foundation. Samples will also be taken from around the perimeter of the existing foundation. Lab turnaround-time shall be as early as possible.

4. Remedial Actions for Contamination Beneath Existing Foundation:

If contamination below the foundation is such that requires future remediation, the Remedial Action Contract (RAC) Contractor shall install a horizontal well (s) beneath the foundation for future remedial use.

The estimated time for installation of the horizontal well is approximately **one week**. This can be coordinated around the tank removal efforts.

The state likes the idea that future site remedial efforts are being considered.

5. RAC Contractor Efforts:

The RAC contractor is presently not on board. NAVSUP's funds will be used to bring the RAC contractor on board unless otherwise directed.

Remedial efforts at this site may be eligible for future ERN funds. If this site is found to be ERN eligible, funds will not be available prior to the FY 2000. ERN funds for FY '99 are already budgeted.

The RAC contractor can be used to coordinate pre-remedial activities with Enterprise, collect tank closure samples, obtain sample analysis, certify data, handle unforeseen environmental issues, prepare closure reports for the state and prepare a Remedial Action Plan (RAP), if required. Note: The tank removal contractor is not required to certify closure data nor submit the report to the FDEP.

6. Available Funds:

The RAC contractor should be brought on board now. It is extremely close to the end of the fiscal year. How long will funds be available? It will be necessary to prepare a statement of work (SOW) for the RAC contractor's efforts.

7. Additional Tanks:

Are soil removal efforts being considered at the other tank locations ... 99, 100, 101?

Will the RAC contractor be required for efforts at those sites also?

Will contaminated soils from all of the tanks be commingled?

DEPARTMENT OF THE NAVY

Memorandum

DATE:

06 OCT. 98

FROM:

BEVERLY S. WASHINGTON (CODE 1848)

TO:

EMMETT BEERS, BHATE ENVIRONMENTAL ASSOCIATES, INC.

SUBJ:

DRAFT CAR ADD FOR NSC FUEL FARM, NAVAL STATION

MAYPORT, DATED SEPTEMBER 29, 1998

1. These are comments on the above subject.

Section #	Comments
	Provide a Table of Contents Include a copy of FDEP's letter responding to the CAR Address each comment in FDEP's letter. Provide a new cover letter for the CAR, dated 12 December 1997, for record purposes. The CAR is entitled 'DRAFT CAR'. Technically FDEP does not review 'Drafts'. The new cover letter will replace the present one same date.
4.0	Type "CONTROL" in title.
5.1 (4 th bullet)	Should be 'exceed' vs 'exceeded'.
6.0 (2 nd bullet)	Modify this paragraph since soils at 10 feet above mean sea level (msl) and below will not be removed during tank removals. The tank foundation at 10 feet above msl will remain in place.
7.0	Review and correct title.
Figure 2	Identify contaminated gw in the legend. Identify corresponding sampling depth for values indicated in data tables for new sampling locations. Show previous sampling data for well # FF-MW- 5. The data on Figure 9 of the CAR did not agree with the data in Table 5 of the CAR.

DEPARTMENT OF THE NAVY

Memorandum

Figure 5 (New) Modify Figure 13 of the CAR (Tank 202 Profile) to include new

sampling data.

Analytical Report Sample ID: FF-MW10-SS-9 Please explain the use of Method

3550 for PAH's

Analytical Report Sample ID: FF-SS-RS-1 Please explain the use of Method

3510 for PAH's

BEVERLY S. WASHINGTON C/1848, (803) 820-5581



Bhate Environmental Associates, Inc. Environmental Engineers & Scientists 1608 13th Avenue, South, Suite 300 Birmingham ■ Alabama ■ 35205 (205) 918-4000 (205) 918-4050 (FAX)

October 30, 1998

Commanding Officer **Environmental Division** Bldg. 191C, N4E4 **Naval Station Mayport** Mayport, Florida 32228-0067

Attention:

Ms. Cheryl Mitchell

Subject:

Addendum to the Contamination Assessment Report

NSC Fuel Farm

Naval Station Mayport

Mayport, Florida

Contract No. N62467-96-0976 BHATE Project No.: 9970082

Dear Ms. Mitchell:

Bhate Environmental Associates, Inc. (BHATE) is pleased to submit an Addendum to the Contamination Assessment Report (CAR) previously sent to the Florida Department of Environmental Protection (FDEP). This addendum report describes activities at the NSC Fuel Farm conducted to address comments about the CAR made by the FDEP.

If you have any questions or need additional information, please contact us at your earliest convenience at 1 (800) 806-4001.

Respectfully submitted,

BHATE ENVIRONMENTAL ASSOCIATES, INC.

Dewey Trapp

Project Geologist

Senior Project Manager

I:\USR\PROJECTS.BEA\1997\9970082\corrADDENDUM TO CAR FUELFARM

Larry D. Schutts
Technical Director

Florida Professional

NO. 497

HINNER D. SCHOOL



TABLE OF CONTENTS ADDENDUM TO THE CONTAMINATION ASSESSMENT REPORT NAVAL STATION MAYPORT NSC FUEL FARM

BEA PROJECT NO.: 9970082

1.0	BACKGR	OUND	1
2.0		MENT ACTIVITIES	
	2.1	Soil Sample Collection	
	2.2	Monitoring Well Installation and Development	2
	2.3	Groundwater Sampling	3
	2.4	Groundwater Flow Direction	3
3.0	RESULTS	S OF THE CONTAMINATION ASSESSMENT	4
	3.1	Soil Analytical Results	4
	3.2	Groundwater Analytical Results	
4.0	QUALITY	Y ASSURANCE/QUALITY CONTROL	5
5.0	SUMMAI	RY AND CONCLUSIONS	4
	5.1	Summary	
	5.2		6
6.0	RECOMM	MENDATIONS	(
7.0	CLOSING	REMARKS	7



TABLE OF CONTENTS (Continued) ADDENDUM TO THE CONTAMINATION ASSESSMENT REPORT NAVAL STATION MAYPORT NSC FUEL FARM

BEA PROJECT NO.: 9970082

TABLES

-:	Monitoring Well Construction Data and Water Level Data
-	Summary of Soil Headspace Analyses
_	Summary of Soil Analytical Results
-	Summary of Groundwater Analytical Results
	-

FIGURES

Figure 1	-	Soil Boring and Monitoring Well Sampling Locations
Figure 2	<u>~</u> .	Soil Analytical Results
Figure 3	-	Monitoring Well Groundwater Analytical Results
Figure 4	-	Water Table Contour Map, June 26, 1998
Figure 5	-	Tank 202 - Profile

APPENDICES

Appendix A	-	FDEP's Letter of Response to the CAR
Appendix B	-	Boring Logs

Appendix C - Laboratory Analysis and Chain of Custody



1.0 BACKGROUND

The assessment site is the NSC Fuel Farm at the Mayport Naval Station in Mayport, Duval County, Florida. The NSC Fuel Farm contains cut and cover bulk fuel storage tanks (Figure 1).

A contamination assessment was conducted at the site between May and October 1997, to determine the source of free petroleum product encountered in monitoring well MPT-16-MWO2S. The affected well lies east of Tank 202 (Figure 1). The results of the contamination assessment concluded that soil and groundwater contamination is essentially localized in an area around Tank 202. The tank and associated piping are the suspected sources of contamination.

A Contamination Assessment Report, dated December 10, 1997, was submitted to the Florida Department of Environmental Protection. Following review of the report, the FDEP issued a letter requesting additional site assessment in the general area around Tank 202. A copy of the letter is included within Appendix A.

2.0 ASSESSMENT ACTIVITIES

Assessment activities conducted at the site included the installation of monitoring wells and the collection of soil and groundwater samples for laboratory analysis. The following is a summary of the site activities.

2.1 Soil Sample Collection

On June 24, 25 and 26, 1998, soil samples were collected at three locations (FF-MW-10, FF-MW-11 and FF-MW-5) adjacent to Tank 202. These were in close proximity to previous soil probe locations GP-19 and GP-25 and to monitoring well MW-5. The soil sample locations are indicated on Figures 1 and 2.

Soil samples were collected at FF-MW-10 and FF-MW-11, during monitoring well installation, using a 24-inch split-spoon sampler and hollow stem augers. Soil samples were collected continuously at FF-MW-10 and at five-foot intervals in FF-MW-11. One sample was collected from a predetermined depth at MW-5. In that case, the sample was taken with a Geoprobe soil sampler, equipped with stainless steel liners.

Following retrieval, the soil samples were examined for visual and olfactory evidence of petroleum hydrocarbons. They were transferred into one-quart decontaminated glass jars, covered with aluminum foil, and allowed to stabilize for five minutes. Volatile organic concentrations were assessed by organic vapor analyzer (OVA) headspace screening techniques. A flame ionization detector (FID) was used in the field to screen the soil gas headspace of each sample. Carbon filters were used with the FID, to aid in distinguishing naturally occurring methane from hydrocarbon vapors.



Soil samples were selected for laboratory analyses, based on FID screening results, from depths of nine feet at FF-MW-10 (FF-MW10-SS-9), nineteen feet at FF-MW-11 (FF-MW11-SS-19), and nine feet at FF-MW-5 (FF-MW5-SS-9). Soil samples submitted for analyses were placed into laboratory supplied clean glass jars, sealed with Teflon-lined lids, and cooled to approximately 4°C. The samples were then delivered, under chain of custody, to Specialized Assays Laboratory in Nashville, Tennessee. They were analyzed for the following parameters:

- Benzene, toluene, ethylbenzene and xylenes (BTEX) by EPA Method 8021B.
- Naphthalene and the 15 method-listed PAHs by EPA Method 8100.
- Florida Petroleum Residual Organics (FL-PRO) by Method TRPH (FDEP).

2.2 Monitoring Well Installation and Development

Monitoring wells were installed at two locations in close proximity to previous soil probes GP-19 and GP-25. The well locations are shown on Figures 1 and 3. Monitoring well construction logs are presented in Appendix A. Pertinent data on the monitoring wells can also be found in Table 1.

The wells were constructed of 2-inch diameter flush-threaded Schedule 40 PVC pipe, with ten (10) feet of 0.01- inch slotted screen. Construction procedures consisted of drilling the augers to a depth within groundwater adequate for monitoring well screen placement. The casing and screen were placed inside the augers, driving the end plug from the augers. The annular space around the screen was filled with 20/30 grade filter sand, as the augers were removed. The sand pack extended to approximately 0.5 feet above the top of the well screen. The upper surface of the sand pack was sealed with bentonite pellets. The thickness of the bentonite seal was approximately 2.0 feet. The bentonite pellets were hydrated with potable water, prior to introducing grout into the borehole. The annular space above the bentonite seal was grouted to the ground surface. A steel manhole assembly was placed over each completed well and secured in the grout column. The PVC well casings were fitted with lockable expansion caps, and the caps were secured with padlocks. A flush mounted, two foot concrete pad was completed at the ground surface of each well.

Representative samples of auger cuttings were collected during drilling activities and an OVA headspace analysis was conducted on each sample. Results of the analyses were utilized in soil disposal. Soils with representative headspace analyses less than 50 ppm were spread on site, in the immediate area of the well. Soils with headspace analytical results greater than 50 ppm were contained within 55-gallon drums for disposal off site.

The monitoring wells were developed by purging with a 2-inch submersible Geopump, which was decontaminated prior to well development. The wells were developed until they were relatively clear of fine-grained sediment.



2.3 Groundwater Sampling

On June 26, 1998, groundwater samples were collected from newly installed monitoring wells FF-MW-10 and FF-MW-11. Prior to sample collection, fluids from each monitoring well were examined for the presence of separate phase petroleum hydrocarbons (free product). To ensure representative groundwater samples, the wells were purged prior to sampling. A peristaltic pump and decontaminated Teflon tubing were used to purge each well. A slow purge quiescent technique was employed. Purging continued until five well volumes had been removed from each well.

The total lead samples were collected utilizing the peristaltic pump. All other groundwater samples were collected using decontaminated Teflon bailers. Groundwater samples were placed in appropriate containers, cooled on wet ice, and transported under chain of custody to Specialized Assays Laboratory. Samples were analyzed for the following:

- Benzene, toluene, ethylbenzene and xylenes (BTEX) and MTBE by EPA Method 602.
- Naphthalene and the 15 method-listed PAHs by EPA Method 610.
- 1,2-dichloroethane and listed Priority Pollutant Volatile Organic Halocarbons by EPA Method 601/602.
- 1,2-dibromoethane (EDB) by EPA Method 601.
- Florida Petroleum Residual organics (FL-PRO) Method TRPH (FDEP).
- Total Lead by EPA Method 6010A.

The glass PAH sample container collected for well FF-MW-11 was broken during shipment to the laboratory and an additional sample was collected on June 30, 1998.

Groundwater evacuated during development and sampling of the monitoring wells was contained in 55-gallon drums. The water was disposed as non-hazardous petroleum contaminated waste.

2.4 Groundwater Flow Direction

All wells were located with respect to horizontal and vertical data. The survey was supervised and certified by a Registered Land Surveyor. All elevations refer to mean sea level (msl).

Groundwater levels were measured within each of the monitoring wells at the site on June 26, 1998. Water-level measurements were obtained with an electronic water-level indicator. They were taken to the nearest 0.01-foot and are referenced to a point on top of the well casing. Relative groundwater elevations were calculated and are summarized with measurements from previous dates in Table 1.



The groundwater levels were used to prepare a water-table contour map (Figure 4). Based on the data shown on the contour map, the primary direction of groundwater movement is to the north and northeast, toward the St. Johns River. That direction is consistent with previous flow direction determinations.

3.0 RESULTS OF THE CONTAMINATION ASSESSMENT

3.1 Soil Analytical Results

Results of the OVA headspace analysis of soil samples taken during the assessment are provided in Table 2. Methane-corrected organic vapor concentrations greater than 50 parts per million (ppm) were measured throughout the sampling interval at FF-MW-10. No headspace concentrations were detected at FF-MW-11.

Results of the laboratory analysis did not detect PAH constituents in any of the soil samples. Ethylbenzene and Total Xylenes were detected in soil samples from FF-MW-5 and FF-MW-10, at concentrations below applicable FDEP regulatory levels. BTEX was not detected at FF-MW-11 above the laboratory method detection limit. An elevated FL-PRO TRPH value was detected in soils taken from boring FF-MW-10. The TRPH value at FF-MW-5 was below the regulatory level of 2500 ppm for soil. TRPH was not detected at FF-MW-11. Soil sample laboratory analytical results are presented in Table 3 and on Figure 2. Copies of the laboratory analytical results and chain-of-custody records are provided in Appendix B.

3.2 Groundwater Analytical Results

Summaries of laboratory analytical results for groundwater samples collected from FF-MW-10 and FF-MW-11 are presented in Table 4 and on Figure 3. Copies of the laboratory analytical reports and chain-of-custody records are provided in Appendix B.

The results did not indicate BTEX or MTBE above the laboratory detection limits. Naphthalene was detected above the FDEP cleanup target level of 20 parts per billion (ppb), in the sample collected from FF-MW-10. The methlynaphthalene constituents detected in both FF-MW-10 and FF-MW-11 are not regulated under groundwater cleanup criteria.

Neither of the TRPH concentrations exceeded the regulatory cleanup criterion of 5 ppm. Concentrations of total lead in groundwater samples collected from these wells were less than the laboratory detection limit.

Fluids in monitoring wells FF-MW-10 and FF-MW-11 were examined for free petroleum product on June 26, 1998, prior to sample collection, and again on June 30, 1998. There was no measurable product thickness in the wells, on either occasion.



Petroleum hydrocarbons in the immediate vicinity of Tank 202 and downgradient areas affect site groundwater. The estimated extent of impacted groundwater is illustrated in Figure 3. Known concentrations of regulated hydrocarbon constituents are generally below levels of concern. Free petroleum product was not observed in the newly installed wells FF-MW-10 and FF-MW-11, or in MPT-16-MWO2S, which had originally contained free product.

4.0 QUALITY ASSURANCE/QUALITY CONTROL

BHATE maintained a stringent QA/QC program for all activities, during data acquisition through report preparation. All appropriate Geoprobe drilling and sampling equipment was decontaminated by appropriate FDEP QA/QC procedures. Auger drilling equipment was steam cleaned, prior to drilling and between each boring. All soil and groundwater sampling equipment was decontaminated with laboratory-grade detergent, appropriate solvent and an alcohol wash. It was then rinsed with deionized and analyte-free water, before each sample collection.

Equipment rinsate samples were collected during soil and groundwater sample collection. Sample FF-SS-RS1 was collected from soil sampling equipment. Sample FF-MW-RS1 was collected from groundwater sampling equipment.

5.0 SUMMARY AND CONCLUSIONS

5. 1 Summary

The following points summarize significant site conditions, based on the results of field and laboratory investigations:

- Corrected soil organic headspace concentrations greater than 50 ppm give evidence
 of excessive kerosene group contamination. Such concentrations were found in soil
 samples collected above the groundwater capillary fringe at well location FF-MW10. Headspace concentrations were not detected in soil samples collected at FFMW-11.
- Ethylbenzene and xylenes were the only BTEX constituents detected in the soil samples. They were found in samples FF-MW10-SS-9 and FF-MW5-SS-9, collected east of Tank 202. The concentrations were below regulatory cleanup target levels. PAH constituents were not detected in any of the samples. Soil sample FF-MW10-SS-9 contained a FL-PRO concentration above the applicable FDEP cleanup target level.
- Naphthalene was detected in groundwater collected from monitoring well FF-MW-10, at a concentration above the FDEP guidance level. BTEX was not detected in



any of the wells.

- TRPH did not exceed the regulatory level of 5 ppm in either FF-MW-10 or FF-MW-11.
- Free petroleum product was not present in either the newly installed monitoring wells in June 1998.
- Total lead was not detected in groundwater samples taken from FF-MW-10 or FF-MW-11. A quiescent sampling technique was used.
- Groundwater measurements were obtained from all of the wells at the site. The direction of groundwater movement appears to be to the north and northeast, toward the St. Johns River and is consistent with previous flow direction determinations.

5.2 Conclusions

- Soil and groundwater contamination is essentially localized in extent to an area around Tank 202. The tank and associated piping remain the suspected sources of contamination.
- FID headspace analyses of samples from above the capillary fringe exceeded the Kerosene Group excessively contaminated soil limit of 50 ppm, at the location of monitoring well FF-MW-10. This affirms previous findings at GP-25 and FF-MW-5. The shallow impact at FF-MW-10 suggests a near-surface release.
- Analyses of site monitoring well samples indicate that groundwater around Tank 202 is not impacted by petroleum hydrocarbons to concentrations greater than applicable FDEP Cleanup Target Levels, except at MPT-16-MW02S (41ppm TRPH) and FF-MW-10 (37 ppb Naphthalene).

6.0 RECOMMENDATIONS

On the basis of findings and conclusions discussed above, Bhate recommends the following:

- Periodic sampling and analysis of groundwater from existing site wells, in order to more firmly establish groundwater quality conditions and the degree to which free product may be distributed downgradient of Tank 202 sources.
- Preparation of a Remedial Action Plan, to address the treatment of soils affected to levels in excess of regulatory limits.



7.0 CLOSING REMARKS

This Addendum to the Contamination Assessment Report has been prepared on behalf of the Department of the Navy, Southern Division for specific application to the subject site. Future environmental conditions at the site can change, subject to changes in operations and land usage. The opinions and findings of this report reflect the conditions apparent at the time the work was performed. New regulations, changes in surrounding land use, altered geologic conditions and other factors may also result in changed site conditions.

The work described in this report has been conducted in accordance with current FDEP UST regulations and with standard industry practice. No other warranty is implied or expressed.



TABLE 1 MONITORING WELL CONSTRUCTION DATA AND WATER LEVEL DATA CONTAMINATION ASSESSMENT REPORT NSC FUEL FARM

NAVAL STATION MAYPORT

WELL NO.	DATE	TOTAL DEPTHS OF WELL BLS (ft.)	TOP OF CASING BLS (ft.)	SURVEYED TOP OF CASING ELEVATION (MSL)*	SCREENED INTERVAL DEPTH BLS (ft.)	DEPTH OF WATER FROM TOP OF CASING (ft.)	ELEVATION OF WATER TABLE (MSL)*
FF-MW-1	6/26/98	18.8	0.17	16.37	8.62-18.12	14.93	1.44
	10/8/97					14.46	1.81
i	7/16/97					14.65	1.72
	6/18/97					14.19	2.18
FF-MW-2	6/26/98	17.4	0.21	18.46	7.37-16.87	13.17	5.29
ĺ	10/8/97					12.83	5.63
	7/16/97					NR	NR
	6/18/97					12.39	6.07
FF-MW-3	6/26/98	14.30	0.24	10.25	4.09-13.59	9.07	1.18
	10/8/97					9.18	1.07
	7/16/97					9.31	.94
	6/18/97					8.41	1.84
FF-MW-4	6/26/98	14.90	0.25	12.15	3.81-13.31	10.55	1.60
	10/8/97					10.11	2.04
	7/16/97					10.28	1.87
Ì	6/18/97					9.86	2.29
FF-MW-5	6/26/98	15.2	0.25	11.83	4.99-14.49	10.56	1.27
	10/8/97					10.42	1.41
Ī	7/16/97					10.65	1.18
	6/18/97					9.78	2.05
FW-MW-6	6/26/98	14.96	0.21	9.91	3.6-13.10	8.54	1.37
	10/8/97		1.100			9.02	.89
4	7/16/97					9.14	.77
	6/18/97					8.19	1.72
FF-MW-7	6/26/98	15.05	0.17	9.43	4.84-14.34	8.30	1.13
	10/8/97					8.34	1.09
	7/16/97					8.50	0.93
	6/18/97			-1		7.62	1.81
FF-MW-8	6/26/98	15.17	0.17	8.98	4.96-14.46	7.85	1.13
	10/8/97					7.71	1.27
ļ ļ	7/16/97					7.78	1.20
ŀ	6/18/97					7.18	1.80

TABLE 1 (CONTINUED) MONITORING WELL CONSTRUCTION DATA AND WATER LEVEL DATA CONTAMINATION ASSESSMENT REPORT NSC FUEL FARM

NAVAL STATION MAYPORT

WELL NO.	DATE	TOTAL DEPTHS OF WELL BLS (ft.)	TOP OF CASING BLS (ft.)	SURVEYED TOP OF CASING ELEVATION (MSL)*	SCREENED INTERVAL DEPTH BLS (ft.)	DEPTH OF WATER FROM TOP OF CASING (ft.)	ELEVATION OF WATER TABLE (MSL)*
FF-MW-9	6/26/98	24.79	0.21	10.08	21.98-24.29	8.58	1.50
	10/8/97					8.99	1.09
	7/16/97					9.15	0.93
	6/18/97					8.26	1.82
FF-MW-10	6/26/98	15.0	0.09	13.31	14.7-15.2	12.02	1.29
FF-MW-11	6/26/98	25.0	0.17	21.45	15.2-24.2	20.03	1.42
MPT16MW02S	6/26/98	15.50	0.28	10.74	5.0-15.0	9.28	1.46
	10/8/97					9.46	1.28
	7/16/97					9.73	1.01
	6/18/97					9.91	0.83
MPT16MW03S	6/26/98	15.50	0.40	11.27	5.0-15.0	10.03	1.24
	10/8/97					9.68	1.59
	7/16/97					9.85	1.42
	6/18/97					9.32	1.95
MPT-8-PO1	6/26/98	15.0	NR	12.89**	10.0-15.0	7.31	5.58
	10/8/97					6.44	6.45
MPT-9-MW03	10/8/97	15.0	NR	11.49**	5.0-15.0	10.32	1.17
MPT-16-MW01I	6/26/98	30.0	NR	12.84**	25-30.0	10.77	2.07
	10/8/97					10.96	1.88
MPT-9-MW01S	6/26/98	20.0	NR	14.39**	5.0-20.0	12.81	1.58
	10/8/97					12.45	1.93

Notes:

NR = Not recorded BLS = Below Land Surface

*= Elevations referenced to MSL (Mean Sea Level)
**= Elevations obtained from previous reports by others

Water level measurements were obtained on June 3, July 16 and October 8, 1997

TABLE 2 SUMMARY OF SOIL HEADSPACE ANALYSES NSC FUEL FARM NAVAL STATION MAYRORT MAYPORT; FLORIDA

Boring	Date	Depth (ft.)	OVA Headspace Unfiltered (ppm)	OVA Headspace Filtered (ppm)	OVA Headspace Corrected (ppm)	Field Notes
FF-MW-10	6/24/98	4	220	1	219	Petroleum odor.
	,	6	360	30	330	Petroleum odor.
		8	650	1	649	Petroleum odor.
		9	1500	2	1498	Petroleum odor.
FF-MW-11	6/25/98	4	0	0	0	No odor.
		9	0	0	0	No odor.
		15	0	0	0	No odor.

Notes:

OVA = organic vapor analyzer ppm = parts per million

TABLE 3 SUMMARY OF SOIL ANALYTI©AL RESULTS NSC FUEL FARM

POLYNUCLEAR ARO	POLYNUCLEAR AROMATIC HYDROCARBONS (EPA Method 8100)in mg/kg						
	FF-MW5-SS-9	FF-MW10-SS-9	FF-MW11-SS-19	Regulatory Levels			
DATE	6/26/98	6/24/98	6/25/98				
PARAMETER							
Naphthalene	BDL	BDL	BDL	8600			
Acenapthene	BDL	BDL	BDL	22000			
Anthracene	BDL	BDL	BDL .	290000			
Fluoranthene	BDL	BDL	BDL	45000			
Fluorene	BDL	BDL	BDL	24000			
Pyrene	BDL	BDL	BDL	40000			
Benzo(a)anthracene	BDL	BDL	BDL	5.1			
Benzo(a)pyrene	BDL	BDL	BDL	0.5			
Benzo(b)fluoranthene	BDL	BDL	BDL	5.0			
Benzo(k)fluoranthene	BDL	BDL	BDL	52			
Chrysene	BDL	BDL	BDL	490			
Dibenzo(a,h)anthracene	BDL	BDL	BDL	0.5			
Indeno(1,2,3-cd)pyrene	BDL	BDL	BDL	5.2			
Acenapthylene	BDL	BDL	BDL	11000			
Benzo(g,h,i)perylene	BDL	BDL	BDL	45000			
Phenanthrene	BDL	BDL	BDL	29000			

TABLE 3- (Continued) SUMMARY OF SOIL ANALYTICAL RESULTS NSC FUEL FARM

PURGEABLE AROMATICS	(EPA Method 8021B)in mg/kg

	FF-MW5-SS-9	FF-MW10-SS-9	FF-MW11-SS-19	Regulatory Levels
DATE ,	6/26/98	6/26/98	6/26/98	
PARAMETER				
Benzene	BDL	BDL	BDL	1.5
Toluene	BDL	BDL	BDL	2000
Ethylbenzene	0.1050	0.5500	BDL	240
Total Xylenes	0.5300	2.650	BDL	290
PETROLEUM HYD	ROCARBONS (Florida	FL-PRO)in mg/kg	g	
TRPH	523	5980	BDL	2500
		Notes:		

Notes:

BDL = Below Detection Limit

Shaded values indicate value exceeding regulatory standard

TABLE 4 SUMMARY OF GROUNDWATER ANALYTICAL RESULTS NSC FUEL FARM NAVAL STATION MAYPORT MAYPORT, FLORIDA

POLYNUCLEAR AROMATIC HYDROCARBONS (EPA Method 610)....in µg/l

PARAMETER	FF-MW-10	FF-MW-11	Regulatory Levels
DATE	6/26/98	6/30/98	
Naphthalene	37.0	BDL	20
2-Methylnaphthalene	81.0	BDL	
1-Methylnaphthalene	67.0	16.0	
Acenaphthylene	BDL	BDL	210
Acenaphthene	BDL	BDL	20
Fluorene	BDL	BDL	280
Phenanthrene	BDL	BDL	210
Anthracene	BDL	BDL	2100
Fluoranthene	BDL	BDL	280
Pyrene	BDL	BDL	210
Benzo(a)anthracene	BDL	BDL	0.2
Chrysene	BDL	BDL	5
Benzo(b)Fluoranthene	BDL	BDL	0.2
Benzo(k)Fluoranthene	BDL	BDL	0.5
Benzo(a)pyrene	BDL	BDL	0.2

TABLE 4 (CONTINUED) SUMMARY OF GROUNDWATER ANALYTICAL RESULTS NSC FUEL FARM NAYAL STATIONMAYPORT MAYPORT, FLORIDA

POLYNUCLEAR AROMATIC HYDROCARBONS (Continued						

Date	6/26/98	6/26/98			
PARAMETER	FF-MW-10	FF-MW-11	Regulatory Levels		
Dibenzo(a,h)Anthracene	BDL	BDL	BDL		
Indeno(1,2,3-c,d)pyrene	BDL	BDL	BDL		
Benzo(g,h,i)perylene	BDL	BDL			
Date	6/26/98	6/26/98			
BTEX COMPOUNDS (METHOL) 8020)in μg/l				
Benzene	BDL	BDL	0.2		
Ethylbenzene BDL Toluene BDL Total Xylenes BDL		BDL	700		
		BDL	1,000		
		BDL	10,000		
МТВЕ	BDL	BDL			
Metals (METHOD 239.2)in m	g/I				
LEAD	BDL	BDL	0.015		
PETROLEUM HYDROCARBON	NS (FL-PRO)in mg/l				
TRPH	2.810	1.110	5		

Notes:

TABLE 4 (CONTINUED) SUMMARY OF GROUNDWATER ANALYTICAL RESULTS NSC FUEL FARM NAVAL STATION MAYPORT MAYPORT, FLORIDA


	MAY	PORT, FLORIDA	
POLYNUCLEAR AROMATIC	HYDROCARBONS (Continued)		
Date	6/26/98	6/26/98	
PARAMETER	FF-MW-10	FF-MW-11	Regulatory Levels
Dibenzo(a,h)Anthracene	BDL	BDL	BDL
Indeno(1,2,3-c,d)pyrene	BDL	BDL	BDL
Benzo(g,h,i)perylene	BDL	BDL	
Date	6/26/98	6/26/98	
BTEX COMPOUNDS (METHO	D 8020)in μg/l		
Benzene BDL Ethylbenzene BDL		BDL	0.2
		BDL	700
Toluene	BDL	BDL	1,000
Total Xylenes BDL MTBE BDL		BDL	10,000
		BDL ·	
Metais (METHOD 239.2)in m	ng/l	•	
LEAD BDL		BDL	0.015
PETROLEUM HYDROCARBO	NS (FL-PRO)in mg/l		
TRPH	2.810	1.110	5


Notes:


TABLE 4 (CONTINUED) SUMMARY OF GROUNDWATER ANALYTIGAL RESULTS NSC FUEL FARM NAVAL STATION MAYPORT MAYPORT, FLORIDA


VOLATILE ORGANICS (EPA Method 601/602) . . . in μg/l


Date	6/26/98	6/26/98	
PARAMETER	FF-MW-10	FF-MW-11	Regulatory Levels
Chlorobenzene	BDL	BDL	
1,2-Dichlorobenzene	BDL	BDL	-
1-3-Dichlorobenzene	BDL	BDL	-
1,4-Dichlorobenzene	BDL	BDL	***
Bromodichloromethane	BDL	BDL	-
Bromoform	BDL	BDL	100
Bromomethane	BDL	BDL	_
Carbon tetrachloride	BDL	BDL	5.0
Chloroehtane	BDL	BDL	-
2-Chloroehtylvinylether	BDL	BDL	-
Chloroform	BDL	BDL	0.1
Chloromethane	BDL	BDL	
Dibromochloromethane	BDL	BDL	
Ethylene Dibromide	BDL	BDL	0.05
Vinyl chloride	BDL	BDL	2.0













Lawren Chiles Governor

Department of Environmental Protection

Twin Toware Building 2500 Blai: Stone Road Taliahassas, Aprida 32366-2400 Virginia E. Wetherell Secretary

January 23, 1998

Ms. Beverly Washington
Department of the Navy, Southern Division
Naval Facilities Engineering Command
2155 Bagle Drive, PO Box 190010
North Charleston, SC 29419-9010

file; car_nacl.dec

RE: Contamination Assessment Report NSC Fuel Farm, Naval Station Mayport, Mayport, HL

Dear Ms. Washington:

I have reviewed the above document dated November 19, 1997 (received December 15, 1997). The report is generally well prepared; however, the following comments should be adequately addressed:

- 1. Sites GP-19 and GP-25 (Figure 9) exhibited high TPH values (1,100 and 14,000 ppm respectively), indicating the possible presence of free product. A shallow monitoring well or piezometer should be installed in the close proximity of both of these locations. They should be evaluated for the presence of free product or in the absence of free product, sampled for the analysis of volatile and semivolatile petroleum constituents.
- 2. At least three soil samples should be collected and analyzed for volatile organic aromatics and PAHs. Some of these may be collected during the installation of monitoring wells or piezometers. The soil samples should be collected from areas with high, medium and low screening results for the site.
- Monitoring well MW02S, on Figure 12, should be identified as exhibiting 41 ppm TPH.
- 4. Please present the results of this additional assessment as a CAR Addendum with updated figures, tables and revised conclusions and recommendations, as necessary. You may use a letter format for the Addendum if you desire. Please insure that the document is properly signed and scaled according to Florida regulations.

Thank you for the opportunity to review this document. For your further information, I am enclosing a copy of the new Chapter 62-770, F.A.C. which addresses petroleum contaminated sites. If you have any questions or need any additional information, please feel free to contact me at 850-921-4230.

"Protect, Conserve and Manage Floride's Environment and Natural Resources"

Printed on recycled paper.



Environmental Engineers & Scientists

MONITORING WELL LOG

BORING NO: FF-MW-10


PROJECT NO: 9970082

PROJECT NAME: NAVSTA MAYPORT ____ CLIENT: U.S. NAVY

PROJECT LOCATION: FUEL FARM

4 1/2 INCH ID HOLLOW STEM AUGER DRILLING MTHD:

SAMPLE MTHD: 24 INCH GEOPROBE SAMPLER



BGS = BELOW GROUND SURFACE

BDL = BELOW DETECTION LIMIT

PAGE: 1 OF: 1



Environmental Engineers & Scientists

MONITORING WELL LOG

BORING NO: FF-MW-11

PROJECT NO: 9970082


PROJECT NAME: NAVSTA MAYPORT CLIENT: U.S. NAVY

PROJECT LOCATION: FUEL FARM

DRILLING MTHD: 4 1/2 INCH ID HOLLOW STEM AUGER

SAMPLE MTHD: 24 INCH GEOPROBE SAMPLER

DATE STARTED: 6/25/98 DATE FINISHED: 6/25/98 ENGINEER/GEOLOGIST: D. TRAPP



BGS = BELOW GROUND SURFACE

BOL = BELOW DETECTION LIMIT

PAGE: 1 OF: 1

SPECIALIZED ASSAYS, INC.



2960 Foster Creighton Dr. P.O. Box 40566 Nashville, TN 37204-0566 Phone 1-615-726-0177

ANALYTICAL REPORT

TATE ENVIRONMENTAL, INC. 5896

408 13TH AVENUE SOUTH

roject: 9970082

oject Name: MAYPORT NAUSTIA

_mpler: DEWEY TRAPP

Lab Number: 98-A75702 Sample ID: FF-MW5-SS-9

Sample Type: Soil

Site ID:

Date Collected: 6/26/98 Time Collected: 12:25 Date Received: 6/30/98


Time Received: 9:00

	*********	· · · · · · · · · · · · · · · · · · ·	Report	guan	Dil	· ·			. 	
Analyte	Result	Units	Linit	Linit	Factor	Date	Tine	Analyst	Hethod 	Batch
URGANIC PARAMETERS										
Benzene	HD.	ng/kg	0.0500	0.0010	50	7/ 9/98	5:59	Ciesielski	8021B	5777
Toluene	ND.	ng/kg	0.0500	0.0010	50	7/ 9/98	5:59	Ciesielski	80218	5777
Ethylbenzene	0.1050	ng/kg	0.0500	0.0010	50	7/ 9/98	5:59	Ciesielski	8021B	5777
Xglenes, total	0.5300	ng/kg	0.1000	0.0010	50	7/ 9/98	5:59	Ciesielski	8021B	5777
TPH-High (Florida Pro)	523.	ng/kg	100.	5.0	10	7/15/98	13:21	K. Phelps	FOEP	6374
Hapthalene	ND.	ng/kg	0.33	0.33	1	7/ 9/98	13:04	Carmichael	8100	6188
Acenapthene	מא	ng/kg	0.33	0.33	1	7/ 9/98	13:04	Carmichael	8100	6188
Anthracene	Ю	ng/kg	0.33	0.33	1	7/ 9/98	13:04	Carmichael	8100	6188
Fluoranthene	ND.	ng/kg	0.333	0.330	1	7/ 9/98	13:04	Carnichael	8100	6188
Fluorene	KD	ng/kg	0.33	0.33	1	7/ 9/98	13:04	Carmichael	8100	6188
Pyrene	HD	ng/kg	0.33	8.33	1	7/ 9/98	13:04	Carnichael	8100	6188
Benzo(a)anthracene	ОК	ng/kg	0.333	0.330	1	7/ 9/98	13:04	Carmichael	8100	6188
Benzo(a)pyrene	ОK	ng/kg	0.33	8.33	1	7/ 9/98	13:04	Carmichael	8100	6188
Benzo(b)fluoranthene	ОЖ	ng/kg	0.33	0.33	1	7/ 9/98	13:04	Carmichael	8100	6188
Benzo(k)fluoranthene	HD	ng/kg	0.33	0.33	1	7/ 9/98	13:04	Carnichael	8100	6188
Chrysene	ЖD	ng/kg	0.33	0.33	1	7/ 9/98	13:04	Carmichael	8100	6188
Dibenzo(a,h)anthracene	КD	ng/kg	0.33	0.33	1	7/ 9/98	13:04	Carnichael	-6100	6188
Indeno(1,2,3-cd)pyrene	КО	ng/kg	0.33	0.33	1	7/ 9/98	13:04	Carmichael	8100	6188
Acenapthylene	жо	rig/kg	0.33	0.33	1	7/ 9/98	13:04	Carmichael	8100	6188
Genzo(g,h,i)perylene	ИD	ng/kg	8.33	0.33	1	7/ 9/98	13:04	Carmichael	8100	6188
Phenanthrene	D	ng/kg	0.33	0.33	1	7/ 9/98	13:04	Carnichael	8100	6188

ND = Not detected at the report limit.

Sample Extraction Data

	Wt/Vol							
Parameter	Extracted	Extract Vol	Date	Analyst	Method			
PAH's	30.0 gm	1.00 Hl	7/ 8/98	Schweikert	3550			





ANALYTICAL REPORT

Laboratory Number: 98-A75702

Sample ID: FF-MW5-SS-9

Page 2

Surrogate	% Recovery	Target Range
surr-a,a,a-Trifluorotolueme	107.	50 150.
surr-o-Terphenyl	i08.	62 109.
Fla Pro Surr., C-35 hydrocarbon	82.	śū 118.
-PAH Surrogate	55.	24 122.

Report Approved By:

Mile H. Rum

Report Date: 7/17/98

Theodore J. Duello, Ph.D., Q.A. Officer Michael H. Dunn, M.S., Technical Director Danny B. Hale, M.S., Laboratory Director



2960 Foster Creighton Dr. P. O. Box 40566 Nashville, TN 37204-0566 Phone 1-615-726-0177

ANALYTICAL REPORT

ATE ENVIRONMENTAL, INC. 5894

.08 13TH AVENUE SOUTH RMINGHAM, AL 35205

oject: 9970082

ject Name: MAYPORT NAUSTIA

npler: DEWEY TRAPP

Lab Number: 98-A75700 Sample ID: FF-MW10-SS-9

Sample Type: Soil

Site ID:

Date Collected: 6/24/98 Time Collected: 15:00 Date Received: 6/30/98

Time Received: 9:00

Analyte	Result	Units	Report Linit	Auan Linit	Dil Factor	Date	Tine	Analyst	Hethod	Natch
DRCANIC PARAMETERS										
Benzene	, dk	ng/kg	0.5000	0.0010	500	7/ 6/98	21: 55	Ciesielski	80218	5777
Toluese	DK	ng/kg	0.5000	0.0010	500	7/ 6/98	21:55	Ciesielski	8021B	5777
Ethylbenzene	0.5500	ng/kg	0.5000	0.0010	500	7/ 6/98	21:55	Ciesielski	8021B	5777
Xylenes, total	2. 650	ng/kg	1.000	0.0010	500	7/ 6/98	21: 55	Ciesielski	8021B	5777
TPH-High (Florida Pro)	5980	ng/kg	400.	5.0	40	7/13/98	15: 53	K. Phelps	FDEP	6374
Wapthalene	ДX	ng/kg	3. 33	0.33	10	7/10/98	15: 37	Carmichael	8100	6188
Acenapthene	ДK	ng/kg	3. 33	0.33	10	7/10/98	15: 37	Carmichael	8100	\$188
Anthracene	ďЯ	ng/kg	3. 33	8. 33	10	7/10/98	15: 37	Carmichael	8100	6188
Fluoranthene	ИD	ng/kg	3. 33	0, 330	10	7/10/98	15: 37	Carmichael	8100	\$188
Fluorene	סא	ng/kg	3. 33	0.33.	10	7/10/98	15: 37	Carmichael	8100	6188
Purene	D	ng/kg	3. 33	0. 33	10	7/10/98	15: 37	Carnichael	8100	6188
Benzo(a)anthracene	ИD	ng/kg	3. 33	0.330	18	7/10/98	15: 37	Carnichael	8100	6188
Benzo(a)pyrene	AD	ng/kg	3. 33	0.33	10	7/10/98	15: 37	Carnichael	8100	6188
Renzo(b)fluoranthene	ВD	ng/kg	3. 33	0.33	10	7/10/98	15: 37	Carnichael	8100	6188
Benzo(k)fluoranthene	סא	ng/kg	3. 33	0.33	10	7/10/98	15: 37	Carnichael	8100	6188
Chrysene	ЖD	ng/kg	3. 33	0.33	10	7/10/98	15: 37	Carmichael	8100	3138
Dibenzo(a,h)anthracene	ИD	ng/kg	3.33	0.33	10	7/10/98	15: 37	Carnichael	8100	6188
Indeno(1,2,3-cd)pyrene	AD OX	ng/kg	3.33	0.33	10	7/10/98	15: 37	Carmichael	8100	6188
Acenapthylene	ND	ng/kg	3. 33	0.33	10	7/10/98	15: 37	Carmichael	8100	6188
Benzo(g,h,i)perylene	ND	ng/kg	3. 33	0.33	10	7/10/98	15: 37	Carmichael	8100	6188
Phenanthrene	ND	ng/kg	3. 33	0. 33	ia	7/10/98	15: 37	Carmichael	8100	6188

ND = Not detected at the report limit.

Parameter	Mt/Vol Extracted	Extract Vol	Date	Analyst	Method
PAH's	30.0 gH	1.00 Hl	7/ 8/98	Schueikert	3550



2960 Foster Creighton Dr. P.O. Box 40566 Nashville, TN 37204-0566 Phone 1-615-726-0177

ANALYTICAL REPORT

Laboratory Number: 98-A75700

Sample ID: FF-MW10-SS-9

Page 2

Surrogate	% Recovery	Target Range
surr-a,a,a-Trifluorotolueme	107.	50 150.
-PAH Surrogate	73.	24 i22.

Report Approved By:

Hale & Kun Report Date: 7/17/98

Theodore J. Duello, Ph.D., Q.A. Officer Michael H. Dunn, M.S., Technical Director Danny B. Hale, M.S., Laboratory Director



2960 Foster Creighton Dr. P.O. Box 40566 Nashville, TN 37204-0566 Phone 1-615-726-0177

ANALYTICAL REPORT

ATE ENVIRONMENTAL, INC. 5896

508 13TH AVENUE SOUTH TRMINGHAM, AL 35205

roject: 9970082

oject Name: MAYPORT NAUSTIA

Impler: DEWEY TRAPP

Lab Number: 98-A75701

Sample ID: FF-MW11-SS-19

Sample Type: Soil

Site ID:

Date Collected: 6/25/98

Time Collected: 12:40


Date Received: 6/30/98

Time Received: 9:00

Analyte	Result	Units	Report Limit	Nuan Linit	Dil Factor	Date	Тіне	Analyst	Method	Katch
DRGAHIC PARAMETERS	Let.									
Benzene	מא	ng/kg	0.0019	0.0010	1	7/ 6/98	22: 31	Ciesielski	80218	5777
Toluese	סא	ng/kg	0.0010	0.0010	1	7/ 6/98	22: 31	Ciesielski	8021B	5777
Ethylbenzene	סא	ng/kg	0.0010	0.0010	i	7/ 6/98	22: 31	Ciesielski	80218	5777
Xylenes, total	ИD	ng/kg	0.0020	0.0010	1	74 6/98	22: 31	Ciesielski	8021B	5777
TPH-High (Florida Pro)	ИD	ng/kg	10.0	5.0	1	7/11/98	10:58	K.Phelps	FDEP	6374
Hapthalene	ЯD	ng/kg	0.33	0.33	i	77 9/98	12: 26	Carmichael	8100	6188
Acenapthene	ак	#g/kg	0.33	0.33	1	7/ 9/98	12: 26	Carnichael	8100	6188
Anthracene	ND D	ng/kg	0.33	0.33	i	7/ 9/98	12: 26	Carmichael	8100	6188
Fluoranthene	ИD	ng/kg	0.333	0.330	1	7/ 9/98	12:26	Carmichael	8100	6188
Fluorese	ND	ng/kg	0.33	0.33	1	7/ 9/98	12: 26	Carnichael	8100	6188
Fyrene	ИD	ng/kg	0.33	0.33	1	77 9798	12: 26	Carnichael	8100	6188
Benzo(a)anthracese	ND.	ng/kg	0.333	0.330	1	7/ 9/98	12: 26	Carmichael	8100	6188
Benzo(a)pyrene	ОK	ng/kg	0.33	0.33	1	7/ 9/98	12: 26	Carmichael	8100	6188
Benzo(b)fluoranthene	В	ng/kg	0.33	0.33	1	7/ 9/98	12: 26	Carnichael	8100	6188
Benzo(k)fluoranthene	ДK	ng/kg	0.33	0. 33	1	7/ 9/98	12: 26	Carnichael	8100	6188
Chrysene	ДЖ	ng/kg	0.33	0.33	1	7/ 9/98	12: 26	Carmichael	8100	6188
Dibenzo(a,h)anthracene	ЖD	ng/kg	0.33	0.33	1	7/ 9/98	12: 26	Carnichael	8100	6188
Indeno(1,2,3-cd)pyrene	ND CIN	ng/kg	0.33	0.33	1	7/ 9/98	12: 26	Carmichael	8100	6188
Acenapthylene	D	rig/kg	0.33	0.33	ī	7/ 9/98	12: 26	Carmichael	8100	6188
Benzo(g,h,i)perylene	מא	ng/kg	0.33	0. 33	i	7/ 9/98	12: 26	Carmichael	8100	6188
Phenanthrene	OK	ng/kg	0.33	0. 33	- 1	7/ 9/98	12: 26	Carmichael	8100	š138

— ND = Not detected at the report limit.

Parameter	Mt/Vol Extracted	Extract Vol	Date	Analyst	Method
PAH's	30.0 дн	1.00 Hl	7/ 8/98	Schueikert	3550





ANALYTICAL REPORT

Laboratory Number: 98-A75701

Sample ID: FF-MW11-SS-19

Page 2

Surrogate	% Recovery	Target Range
surr-a,a,a-Trifluorotoluene	139.	50 150.
surr-o-Terphenyl	91.	62 109.
Fla Pro Surr., C-35 hydrocarbon	76.	60 118.
PAH Surrogate	38.	24 122.

Report Approved By:

Mile &- Run Report Date: 7/17/98

Theodore J. Duello, Ph.D., Q.A. Officer Michael H. Dunn, M.S., Technical Director Danny B. Hale, M.S., Laboratory Director



2960 Foster Creighton Dr. P. O. Box 40566 Nashville, TN 37204-0566 Phone 1-615-726-0177

ANALYTICAL REPORT

ATE ENVIRONMENTAL, INC. 5

OB 13TH AVENUE SOUTH RMINGHAM, AL 35205

oject: 9970082

bject Name: MAYPORT NAUSTIA

impler: DEWEY TRAPP

Lab Number: 98-A75703 Sample ID: FF-SS-RS-1 Sample Type: Water

Site ID:


Date Collected: 6/26/98 Time Collected: 10:35 Date Received: 6/30/98

Time Received: 9:00

		20								
Analyte	Result	Units	Report Limit	Quan Linit	Dil Factor	Date	Tine	Analyst	Hethod	Batch
ORGANIC PARAMETERS										
Benzene	ОК	ug/1	1.0	1.0	1	71 6/98	17:48	T. Johnson	602	6645
Toluene	מא	ug/l	1.0	1.0	1	7/ 6/98	17:48	T. Johnson	602	6645
Ethylbenzene	NO.	ug/l	1.0	1.0	1	77 6798	17:48	T. Johnson	602	6645
Xylenes, total	סא	ug/l	1.0	1.0	1	7/ 6/98	17:48	T. Johnson	602	6645
Kaphthalene	AD.	ug/l	5.0	5.0	1	7/ 8/98	10:12	H. Goodrich	610	5933
Acenapthene	AD.	ug/1	5.0	5.0	1	77 8798	10:12	H. Goodrich	610	5933
Anthracene	HD.	ug/l	5.0	5.0	1	77 8798	10:12	M. Goodrich	610	5933
Fluoranthene	ЯD	ug/l	5.0	5.0	1	7/ 8/98	10:12	M. Goodrich	610	5933
Fluorene	ВD	ug/1	5.0	5.0	1	7/ 8/98	10:12	M. Goodrich	610	5933
Pyrene	HD	ug/l	5.0	5.0	1	7/ 8/98	10:12	M. Goodrich	610	5933
:Benzo(a)anthracene	KD	ug/l	5.0	5.0	1	7/ 8/98	10:12	H. Goodrich	610	5933
Benzo(a)pyrene	КĐ	ug/l	5.0	5.0	1	7/ 8/98	10:12	M. Goodrich	610	5933
Benzo(b)fluoranthene	ЯD	ug/l	5.0	5.0	1	7/ 8/98	10:12	M. Goodrich	610	5933
Benzo(k)fluoranthene	ИD	ug/l	5.0	5.0	1	7/ 8/98	10:12	M. Goodrich	610	5933
Chrysene	RD	ug/l	5.0	5.0	1	7/ 8/98	10:12	M. Goodrich	610	5933
Dibenzo(a,h)anthracene	КD	ug/1	5.0	5.0	1	7/ 8/98	10:12	M. Goodrich	610	5933
Indeno(1,2,3-cd)pyrene	ОК	ug/1	5.0	5.0	. 1	7/ 8/98	10:12	M. Goodrich	610	5933
Acenapthylene	КD	ug/l	5.0	5.0	1	7/ 8/98	10:12	M. Goodrich	610	5933
Benzo(g,h,i)perylene	КD	ug/I	5.0	5.0	1	7/ 8/98	10:12	M. Goodrich	610	5933
1-Methylnapthalene	Ю	ug/1	5.0	5.0	1	7/ 8/98	10:12	M. Goodrich	610	5933
2-Methylnapthalene	ФK	ug/l	5.0	5.0	. 1	7/ 8/98	10:12	M. Goodrich	610	5933
Phenanthrene	NO	ug/l	5.0	5.0	1	7/ 8/98	10:12	M. Goodrich	610	5933

ND = Not detected at the report limit.

Parameter	Ht/Vol Extracted	Extract Vol	Date	Analyst	Method
FAH's	980. ml	1.00 Hl	7/ 2/98	Fitzwater	3510





ANALYTICAL REPORT

Laboratory Number: 98-A75703

Sample ID: FF-SS-RS-1

Page 2

Surrogate	% Recovery	Target Range	
BTEX/GRE Surr., a,a,a-trifluorotoluene	87.	50 150.	
FID Surr., a,a,a-trifluorotoluene	99.	50 150.	
Hall Surr., 2-chloropropane	88.	61 132.	
Hall Surr., chloroprene	90.	64 130.	
Hall Surr., 1-chloro-3-fluorobenzene	89.	65. - 132.	
PAH Surrogate	44.	33 123.	

Report Approved By:

Mulad A. Report Date: 7/17/98

Theodore J. Duello, Ph.D., Q.A. Officer Michael H. Dunn, M.S., Technical Director Danny B. Hale, M.S., Laboratory Director

3=1	-14	-r:	=		1					100 000		1			1		NO.: 00001	
Environmenta	I Engineers a	nd Scien	tists	10	5402	CHA]	IN-OF-	·CU	ST	OI	Y					,	Page: 1 of 1	
1608 13th Aven Birmingham, Ala	ue South	#5896		10									<u> </u>	4- /1	1	7	Preserved (Code)	_
(205) 918-4000	(FAX) (205) 918											TVE	25/ 4	44 y	5		lced (yes/no)	
PROJECT NO.:20	70082 F	PROJECT NA	ME:	nAy	PORT NAV	STA) Ful	EL FAM	m	/c	ONTAINE	RS		The state of	10		/ /	Code: A - None B - HN03	
P.O. NO.:	L	AB DESTIN	ATION:	56	ecializa	D ASS	465			//	/ /	W A	12 E		/ /	/ /	C - H ₂ SO4 D - NaOH	
SAMPLER(#) NAM	" Dew	ey 1	RX	da)		y ≅ SPO	/	' /	/ , /		ي وه و	70%	¥ /	/		E - HCI F -	
TITLE:		1		7 / .	Sample No. /		SOIL WATER SOUD OTHER		/	Type.	E	S E	E	E E		ģ /		
Lab Cods — for	only Dale	Time	Con to		Sample No./ Sample Location	i 1			/ 20	/ 1/2/	/ 23	/ E 3	/ E \$	/ E 3	/ E 3		REMARKS	
7570c	6/24/58	1500	V	FF	mw10-	-359	\\ \alpha \\ \al	1 2	207	G	V	V	~					
100	dists8	1240	1 1	FF	MW10- MW5	-5519	Ø000			G	/	~						
757.02	6/24/98	1775	V	FF	=-MW5	-859	Ø D D D	2	207	G	/		V					
		,				4	0000	1							4.			
							0000	1										
					EGENT.	}}	مممم	1										-
					JUL 2 3 19	90	مومو	i										
				HAT	E EXVIDOR	IMENTAL	0000											
			\parallel		- 10-10-10-10-10-10-10-10-10-10-10-10-10-1		0000											
							0000											
			Ш.	<u> </u>	1				<u> </u>									
Relinquished by:	(Signature): I	Date	-	Time:	Received by:	(Signature):	Date:	Time:	LAE	з сомм	ENTS							
1 ly der	was	6/29	k1/	700	(
Relinquished by:	Signature):			Time:	Received by:	(Signature):	Date:	Time:		JARKS (511	DIE CUI	IDDING I	UETHOD.	CAUDIC CONTAINED TYPE	
										tle Into			_	PLE SHI			SAMPLE CONTAINER TYPE	<u>.</u>
Relinquished by:	(Signature):	Date		Ilme:	Received for La		_Date:	Ilme:	-	served:	100		1	id Delly: (apecify		0	P = Plastic G = Glass	
					M. Box	4/	6/30/98	9:00	Olh	lled: er:	4C	. 0		er (spec		0	GA = Glass Amber	
The same of the same of the same		40.00					Security Commence										the second of th	



2960 Foster Creighton Dr. P.O. Box 40566 Nashville, TN 37204-0566 Phone 1-615-726-0177

ANALYTICAL REPORT

TE ENVIRONMENTAL, INC. 5896

08 13TH AVENUE SOUTH

mject: 9970082

ject Name: MAYPORT NAUSTIA

impler: DEWEY TRAPP

Lab Number: 98-A75705 Sample ID: FF-MW-10 Sample Type: Water

Site ID:

Date Collected: 6/26/98 Time Collected: 11:25 Date Received: 6/30/98 Time Received: 9:00

Report กรบมิ Dil Analyte Result Units Linit Linit Factor Date Time Analyst Method Natch *DRGANIC PARAMETERS* Florida Pro 2810 ug/1 202. 100. 1 7/12/98 4:47 K. Phelps FDEP 5685 aphthalene 37. Ū ug/1 5.0 5.0 1 7/ 8/98 11:25 H. Goodrich 610 5933 ncenapthene ND. ug/1 5.0 5.0 1 7/ 8/98 11:25 H. Goodrich 610 5933 Anthracene KD ug/l 5.0 5.0 1 7/ 8/93 11:25 M. Goodrich 310 5933 luoranthene dk ug/l 5.0 5.0 1 7/ 8/98 11:25 M. Goodrich 610 5933 luorene DK ug/l 5. Ū 5.0 1 7/ 8/98 11:25 M. Goodrich 610 5933 Purene ЯD Uq/1 5.0 5.0 1 7/ 8/98 11: 25 M. Goodrich 610 5933 Renzo(a)anthracene **UK** ug/l 5.0 5.0 1 7/ 8/98 11:25 M. Goodrich 610 5933 lenzo(a)pyrene ND) Ug/1 5.0 5.0 1 7/ 8/98 11:25 M. Goodrich 610 5933 Benzo(b)fluoranthene ЖD ug/l 5.0 5.0 1 7/ 8/98 11:25 M. Goodrich 610 5933 Benzo(k)fluoranthene DX ug/1 5.0 5.0 1 7/ 8/98 11:25 M. Goodrich 610 5933 :hrusene DK uq/1 5.0 5.0 1 7/ 8/98 11:25 M. Goodrich 610 5933 Dibenzo(a,h)anthracene DK ug/l 5.0 5.0 1 7/ 8/98 11: 25 M. Goodrich 610 5933 Indeno(1,2,3-cd)pyrene ND ug/l 5.0 5.0 1 7/ 8/98 11:25 M. Goodrich 610 5933 Acenapthylene MD ug/l 5.0 5.0 1 7/ 8/98 11:25 M. Goodrich 610 5933 Benzo(g,h,i)perylene ЯD ug/1 5.0 5.0 1 7/ 8/98 11:25 M. Goodrich 610 5933 1-Methylnapthalene 67.0 ug/1 5.0 5.0 1 7/ 8/98 11:25 M. Goodrich 610 5933 2-Methylnapthalene 81.0 ug/1 5.0 5.0 1 7/ 8/98 11:25 M. Goodrick 610 5933 Phenanthrene ND Uq/1 5.0 5.0 1 7/ 8/98 11:25 M. Goodrich 610 5933 *VOLATILE DREAKICS by ECX Benzene KD. Uq/1 1.0 1.0 1 7/ 2/98 17:27 E. Snith 602 2641 Chlorobenzene ND ug/l 1.0 1.0 1 7/ 2/98 17:27 E. Snith 602/601 2641 1,2-Dichlorobenzene ND ug/l 1.0 1.0 17:27 1 7/ 2/98 E. Snith 602/601 2641 1,3-Dichlorobenzene ND ug/l 1.0 1.0 1 7/ 2/98 17:27 E. Snith 602/601 2641 1,4-Dichlorobenzene **QK** ug/I 1.0 1.0 1 7/ 2/98 17:27 E. Snith 602/601 2641 Ethylbenzene XC: ug/1 1.0 1.0 1 7/ 2/98 17:27 E. Snith 602 2641 Toluene ND ug/1 1.0 1.0 1 7/ 2/98 17:27 602 E. Smith 2641 n,p-Xylenes ND ug/l 1.0 1.0 1 7/ 2/98 17:27 E. Snith 602 2641 o-Xylene ND ug/1 1.0 1.0 1 7/ 2/98 17:27 E. Snith 602 2641 Bronodichloromethane ND. ug/l 1.0 1.0 1 7/ 2/98 17:27 E. Snith 601 2641 Bronoforn KD ug/1 1.0 1.0 1 7/ 2/98 17:27 E. Snith 601 2641 Bronomethane ND ug/I 1.0 1.0 1 7/ 2/98 17:27 E. Smith 601 2641 Carbon tetrachloride dk Ug/1 1.0 1.0 1 7/ 2/98 17:27 E. Snith 601 2641 Chloroethane MD U4/1 1.0 1.0 1 7/ 2/98 17:27 E. Snith 601 2641 2-Chloroethylvinylether ИD ug/l 1.0 1.0 7/ 2/98 17:27 E. Snith 601 2641



2960 Foster Creighton Dr. P.O. Box 40566 Nashville, TN 37204-0566 Phone 1-615-726-0177

ANALYTICAL REPORT

Laboratory Number: 98-A75705

Sample ID: FF-MW-10

Page 2

nalyte	Result	Units	Report Limit	Quan Linit	0il Factor	Date	Tine	Analyst	Hethod	Batch
Chloroforn	ЖD	ug/1	1.0	1.0	1	7/ 2/98	17:27	E. Snith	601	2641
aloromethane	OK	ug/1	1.0	1.0	1	7/ 2/98	17:27	E. Smith	601	2641
vibronochloromethane	ND OH	ug/1	1.0	1.0	1	7/ 2/98	17:27	E. Snith	601	2641
Ethylene Dibronide	ND	ug/1	1.0	1.0	1	7/ 2/98	17:27	E. Snith	601	2641
ingl chloride	ND ON	ug/1	1.0	1.0	1	7/ 2/98	17:27	E. Snith	601	2641
_ichlorodifluoromethame	HD.	ug/l	1.0	1.0	i	7/ 2/98	17:27	E. Snith	601	2641
1,1-Dichloroethane	MD.	ug/l	1.0	1.Ū	1	7/ 2/98	17:27	E. Snith	601	2641
7,2-Dichloroethane	ND.	ug/l	1.0	1.0	1	7/ 2/98	17:27	E. Smith	601	2641
,1-Dichloroethene	ФK	ug/1	1.0	1.0	1	7/ 2/98	17:27	E. Smith	601	2641
cis-1,2-Dichloroethene	NO.	ug/l	1.0	1.0	1	7/ 2/98	17:27	E. Smith	601	2641
trans-1,2-Dichloroethene	KD.	ug/l	1.0	1.0	1	7/ 2/98	17:27	E. Smith	601	2641
,2-Dichloropropane	KD	ug/1	1.0	1.0	1	7/ 2/98	17:27	E. Smith	601	2641
cis-1,3-Dichloropropene	KD OK	ug/1	1.0	1.0	1	7/ 2/98	17:27	E. Snith	601	2641
trans-1,3-Dichloropropene	KD.	ug/1	1.0	1.0	1	7/ 2/98	17:27	E. Smith	601	2641
ethylene chloride	ND	ug/1	1.0	1.0	1	7/ 2/98	17:27	E. Smith	601	2641
,1,2,2-TetrachLoroethane	KD.	ug/1	1.0	1.0	1	7/ 2798	17:27	E. Smith	601	2641
Tetrachloroethene	ND	ug/1	1.0	1.0	1	7/ 2/98	17:27	E. Smith	601	2641
1,1,1-TrichLoroethane	KD	ug/1	1.0	1.0	1	77 2/98	17:27	E. Smith	601	2641
.,1,2-TrichLoroethane	מא	ug/I	1.0	1.0	1.	7/ 2/98	17:27	E. Snith	681	2641
Trichloroethene	ND	ug/l	1.0	1.0	1	7/ 2/98	17:27	E. Smith	601	2641
Trichlorofluoromethane	KD:	ยฐ/1	1.0	1.0	1		17:27	E. Snith	601	2641
-×HETALS×										
Lead	מא	mg/1	0.0030	0.0030	1	7/ 3/98	10:10	R. Kelley	239.2	2815

iD = Not detected at the report limit.

Parameter	Wt/Vol Extracted	Extract Vol	Date	Analyst	Method
PAH's	1000 Hl	1.00 ml	7/ 2/98	Fitzuater	3510
Fla Pro	990. Hl	2.0 ml	7/ 3/98	Schueikert	FDEP

Surrogate	% Recovery	Target Range
Fla Pro Surr., O-Terphenyl Fla Pro Surr., C-35 Hydrocarbon PID Surr., a,a,a-trifluorotoluene Hall Surr., 2-chloropropane Hall Surr., chloroprene	101. 93. 99. 91. 93.	82 142. 55 118. 50 150. 61 132. 64 130.



2960 Foster Creighton Dr. P.O. Box 40566 Nashville, TN 37204-0566 Phone 1-615-726-0177

ANALYTICAL REPORT

Laboratory Number: 98-A75705

Sample ID: FF-MW-10

Page 3

urrogate	% Recovery	Target Range
all Surr., 1-chloro-3-fluorobenzeme	90.	65 132.
.AH Surrogate	42.	33 123.

Report Approved By:

Mule 1 A. Russe

Report Date: 7/17/98

Theodore J. Duello, Ph.D., Q.A. Officer Michael H. Dunn, M.S., Technical Director Danny B. Hale, M.S., Laboratory Director



ANALYTICAL REPORT

TITE ENVIRONMENTAL, INC. 5896

408 13TH AVENUE SOUTH TRAINGHAM, AL 35205

roject: 9970082

) ject Name: MAYPORT NAUSTIA

Linpler: DEWEY TRAPP

Lab Number: 98-A75706 Sample ID: FF-MW-11 Sample Type: Water

Site ID:

Date Collected: 6/26/98 Time Collected: 12:10 Date Received: 6/30/98 Time Received: 9:00

Analyte	Result	Units	Report Limit	Ruan Limit	Dil Factor	Date	Тіне	Analyst	Method	[katc]
ORGANIC PARAMETERS										
Florida Pro	1110	ug/1	204.	100.	1	7/12/98	7:12	K.Phelps	FDEP	5685
VOLATILE DREAMICS by GC									15	
Benzene	ЖO	ug/1	1.0	1.0	1	7/ 2/98	18: 37	E. Smith	602	2641
Chlorobenzene	ЖD	ug/l	1.0	1.0	i	7/ 2/98	18: 37	E. Snith	602/601	2641
1,2-Dichlorobenzene	ND	84/I	1.0	1.0	i	7/ 2/98	18: 37	E. Smith	602/601	2641
1,3-Dichlorobenzene	ИD	ug/l	1.0	1.0	i	7/ 2/98	18: 37	E. Smith	602/601	2641
1,4-Dichlorobenzene	ЖD	ug/l	1.0	1.0	i	7/ 2/98	18: 37	E. Snith	602/601	2641
Ethylbenzene	HD.	ug/1	1.0	1.0	1	7/ 2/98	18: 37	E. Smith	6027 601	2641
Toluene	ЖD	ug/l	1.0	1.0.	1	7/ 2/98	18:37	E. Snith	602	2641
n,p-Xylenes	ЖО	ug/1	1.0	1.0	1	7/ 2/98	18: 37	E. Smith	602 602	2641
o-Xylene	ND.	ug/1	1.0	1.0	1	7/ 2/98	18: 37	E. Smith	602	2641
-Bronodichloromethame	ЖD	ug/1	1.0	1.0	1	7/ 2/98	18:37	E. Snith	601	2641
Bronoforn	HD	ug/1	1.0	1.0	1	7/ 2/98	18:37	E. Snith	601	
Bronomethane	ОЖ	ug/l	1.0	1.0	1	7/ 2/98	18:37	E. Smith	601	2641
Carbon tetrachloride	ND OK	ug/l	1.0	1.0	1	7/ 2/98	18: 37			2641
Chloroethane	מא	ug/l	1.0	1.0	1			E. Snith E. Snith	601 <i>6</i> 01	2641 2641
2-Chloroethylvinylether	ОК	ug/l	1.0	1.0	1	7/ 2/98	18: 37	E. Smith	601	
Chloroform	ЖО	ug/1	1.0	1.0	1	7/ 2/98	18: 37 18: 37			2641
Chloromethane	HD OH	ug/1	1.0	1.0	1	7/ 2/98		E. Smith	601	2641
Dibronochloromethane	AD.	ug/l	1.0	1.0	1	7/ 2/98	18:37	E. Smith	601	2641
Ethylene Dibronide	KD -	ug/1	1.0	1.0	1	7/ 2/98	18: 37	E. Snith	601	2641
-Vinyl chloride	ND CK	ug/l	1.0	1.0	1	7/ 2/98	18: 37	E. Snith	601	2641
Dichlorodifluoromethane	KD.	ug/l	1.0	1.0	1	7/ 2/98	18:37	E. Smith	601	2641
1,1-Dichloroethane	מא		1.0	1.0	1	7/ 2/98	18: 37	E. Smith	601	2641
1,2-Dichloroethane	ND OK	ug/l ug/l	1.0	1.0	1	7/ 2/98	18: 37	E. Smith	601	2641
1,1-Dichloroethene	KD OH	ug/l	1.0			7/ 2/98	18: 37	E. Smith .	601	2641
cis-1,2-Dichloroethene	NO.	-		1.0	1	7/ 2/98	18:37	E. Smith	601	2641
trans-1,2-Dichloroethene	KD OX	ug/1	1.0	1.0	1	7/ 2/98	18: 37	E. Smith	601	2641
1,2-Dichloropropane	KD KD	ug/l	1.0	1.0	1	7/ 2/98	18: 37	E. Smith	601	2641
cis-1,3-Dichloropropene		ug/I	1.0	1.0	1	7/ 2/98	18: 37	E. Smith	601	2641
trans-1,3-Dichloropropene	OK OK	ug/1	1.0	1.0	1	7/ 2/98	18: 37	E. Smith	601	2641
Methylene chloride	KD OX	ug/l	1.0	1.0	1	7/ 2/98	18: 37	E. Smith	601	2641
	KD.	ug/l	1.0	1.0	1	7/ 2/98	18:37	E. Smith	601	2641
1,1,2,2-Tetrachloroethane Tetrachloroethene	ЖO	ug/1	1.0	1.0	1	7/ 2/98	18:37	E. Smith	601	2641
	КO	ug/l	1.0	1.0	1	7/ 2/98	18: 37	E. Smith	601	2641
1,1,1-Trichloroethane	КD	ug/l	1.0	1.0	1	77 2798	18:37	E. Snith	601	2641



2960 Foster Creighton Dr. P.O. Box 40566 Nashville, TN 37204-0566 Phone 1-615-726-0177

ANALYTICAL REPORT

Laboratory Number: 98-A75706

Sample ID: FF-MW-11

Page 2

alyte	Result	Units	Report Limit	Ruan Linit	Dil Factor	Date	Tine	Analyst	Method	Ratch
1.1,2-Trichloroethane	DK DK	ug/1	1.0 1.0	1.0 1.0	1	7/ 2/98 7/ 2/98		E.Smith E.Smith	601 601	2641 2641
. ichlorofluoromethane	ND ND	ug/l ug/l	1.0	1.0	i	7/ 2/98		E. Smith	601	2641
ETALS*	ОК	ng/1	. 0.0030	0.0030	1	7/ 3/98	10:10	R. Kelley	239.2	2815

|" = Not detected at the report limit.

Sample Extraction Data

	Wt/Vol				
Parameter	Extracted	Extract Vol	Date	Analyst	Method
————					
Fla Pro	980. Hl	2.0 HI	7/ 3/98	Schueikert	FDEP

Súrrogate	% Recovery	Target Range	
a Pro Surr., O-Terphenyl	127.	82 142.	
Fla Pro Surr., C-35 Hydrocarbon	92.	55 118.	*
D Surr., a,a,a-trifluorotolueme all Surr., 2-chloropropame	98. 85.	50 150. 61 132.	
Hall Surr., chloroprene "all Surr., 1-chloro-3-fluorobenzene	91. 85.	64 130. 65 132.	-

Report Approved By:

Metal A. Russe

Report Date: 7/17/98

Theodore J. Duello, Ph.D., Q.A. Officer Michael H. Dunn, M.S., Technical Director Danny B. Hale, M.S., Laboratory Director



2960 Foster Creighton Dr. P.O. Box 40566 Nashville, TN 37204-0566 Phone 1-615-726-0177

ANALYTICAL REPORT

HATE ENVIRONMENTAL, INC. 5894

3 13TH AVENUE SOUTH HMINGHAM, AL 35205

Lab Number: 98-A76312

Sample ID: FF-MW-11

Sample Type: Water

Date Collected: 6/30/98

Site ID:

Time Collected: 8:47

√_ject:

oject Name: NAS MAYPORT FUEL FARM

Date Received: 7/ 1/98 Time Received: 9:00

pler:

			Report	สบาล	Dil					
nalyte	Result	Units	Linit	Linit	Factor	Date	Tine	Analyst	Method	Ratch
						~~~~~		~	N2	
GREANIC PARAMETERS*										
aphthalene	ND	ug/l	5.0	5.0	1	7/ 8/98	0: 26	M. Goodrich	610	5936
Acenapthene	ND .	ug/1	5.0	5.0	1	7/ 8/98	0: 26	M. Goodrich	\$10	5936
Inthracene	ЖÐ	uq/1	5.0	5.0	i	77 8798	0: 26	n. Goodrich	610	5936
luoranthene	ЯD	ug/l	5.0	5.0	1	7/ 3/98	0:26	M. Goodrich	610	5936
Fluorene	AD	ug/1	5.0	5.0	1	7/ 8/98	0: 26	M. Goodrich	610	5936
Fyrene	ОК	ug/1	5.0	5.0	1	7/ 8/98	0: 26	M. Goodrich	610	5936
enzo(a)anthracese	ЖD	ug/1	5.0	5.0	1	7/ 8/98	0:26	M. Goodrich	<b>š10</b>	5936
penzo(a)pyrene	ЯÐ	ug/1	5.0	5.0	1	7/ 8/98	0:26	M. Goodrich	610	5936
Benzo(b)fluoranthene	ЖD	ug/1	5.0	5.0	1	7/ 8/98	0: 26	M. Goodrich	610	5936
(enzo(k)fluoranthene	HD	ug/1	5.0	5.0	1	77 8798	0:26	M. Goodrich	610	5936
hrysene	HD	ug/l	5.0	5.0	1	7/ 8/98	0: 26	M. Goodrich	610	5936
Dibenzo(a,h)anthracene	ИD	ug/l	5.0	5.0	1	7/ 8/98	0:26	M. Goodrich	610	5936
Tindeno(1,2,3-cd)pyrene	ФК	ug/l	5.0	5.0	1	77 8/98	0:26	M. Goodrich	810	5936
Acenapthylene	<b>AD</b>	ug/l	5.0	5.0	1	7/ 8/98	8: 26	H. Goodrich	610	5936
Benzo(g,h,i)perylene	HD	ug/1	5.0	5.0	i	7/ 8/98	0: 26	M. Goodrich	618	5936
_1-Methylnapthalene	16.0	ug/1	5.0	5.0	1	7/ 8/98	0:26	M. Goodrich	610	5936
:-Methylnapthalene	ND OK	ug/l	5.0	5.0	1	7/ 8/98	0:26	M. Goodrich	310	5936
Thenauthrene	AD.	ug/1	5.0	5.0	1	7/ 8/98	0:26	M. Goodrich	610	5936

40 = Not detected at the report limit.

#### Sample Extraction Data

 Surrogate	÷.		X Recovery	Targe	t Range	
PAH's	1000 н1	1.00 Hl	7/ 7/98	Fitzuater	3510	
Farameter	Wt/Vol Extracted	Extract Vol	Date 	Analyst	Method	

PAH Surrogate

47.

33. - 123.

2960 Foster Creighton Dr. P.O. Box 40566 Nashville, TN 37204-0566 Phone 1-615-726-0177

#### ANALYTICAL REPORT

Laboratory Number: 98-A76312

Sample ID: FF-MW-11

Page 2

Surrogate

% Recovery

Target Range

Report Approved By:

Report Date: 7/

7/ 8/98

Theodore J. Duello, Ph.D., Q.A. Officer Michael H. Dunn, M.S., Technical Director Danny B. Hale, M.S., Laboratory Director



# ANALYTICAL REPORT

TE ENVIRONMENTAL, INC. 5894

OS 13TH AVENUE SOUTH

n-ject: 9970082

ject Name: MAYPORT NAUSTIA

impler: DEWEY TRAPP

Lab Number: 98-A75704 Sample ID: FF-MW-RS-1 Sample Type: Water

Site ID:

Date Collected: 6/26/98 Time Collected: 10:45 Date Received: 6/30/98 Time Received: 9:00

Report Auan Dil Analyte Result Units Linit Linit Factor Date Tine Analyst Hethod Ratch *URGANIC PARAMETERS* Florida Pro dk ug/1 202. 100. 1 7/12/93 3:59 K. Phelps FDEP 5685 aphthalene ND ug/1 5.6 5.0 1 7/ 8/98 10:48 M. Goodrich 610 5933 ncenapthene MD ug/1 5.6 5.0 1 7/ 8/98 10:48 M. Goodrich 610 5933 Anthracene ND uq/1 5.6 5.0 7/ 8/98 10:48 M. Goodrich 610 1 5933 luoranthene ND ug/1 5.6 5.0 İ 7/ 8/98 10:48 H. Goodrich 5933 Luorene ND ug/l 5.6 5.0 ŧ 7/ 8/98 10:48 M. Goodrich 610 5933 Furene ND Ug/1 5.6 5.0 1 7/ 3/98 10:48 M. Goodrich 610 5933 enzo(a)anthracene KD uq/1 5.6 5.0 1 7/ 8/98 M. Goodrich 10:48 610 5933 enzo(a)pyrene ND uq/1 5.6 5.0 1 7/ 8/98 10:48 M. Goodrich 610 5933 Benzo(b)fluoranthene KD Ug/1 5.6 5.0 1 7/ 8/98 10:48 M. Goodrich 610 5933 Renzo(k)fluoranthene ND Ug/1 5.6 5.0 1 7/ 8/98 10:48 M. Goodrich 610 5933 hrysene KD ug/l 5.6 5.0 1 7/ 8/98 10:48 M. Goodrich 610 5933 wibenzo(a,h)anthracene ΝĎ uq/1 5.6 5.0 1 7/ 8/98 10:48 M. Goodrich 610 5933 Indeno(1,2,3-cd)pyrene ND uq/1 5. 6 5.0 1 7/ 8/98 10:48 H. Goodrich 610 5933 cenapthylene KD 5.6 5.0 ug/1 1 7/ 8/98 10:48 M. Goodrich 610 5933 enzo(g,h,i)perylene ND ug/1 5.6 5.0 1 7/ 3/98 10:48 610 M. Goodrich 5933 1-Methylnapthalene DK ug/1 5.6 1 5.0 7/ 8/98 10:48 M. Goodrich 610 5933 -Methylnapthalene DK ug/1 5.6 5.0 1 7/ 8/98 10:48 M. Goodrich 610 5933 henanthrene KD uq/1 5.6 5.0 1 7/ 8/98 10:48 M. Goodrich 610 5933 *UDLATILE DREAKIES by GC* enzene KD Uq/1 1.0 1.0 1 7/ 2/98 16:50 E. Snith 602 2641 chlorobenzene CH ug/1 1.0 1.0 1 7/ 2/98 16:50 E. Snith 602/601 2641 1,2-Dichlorobenzene ND uq/I 1.0 1.0 1 7/ 2/98 16:50 602/601 E. Snith 2641 .,3-Dichlorobenzene КD ug/1 1.0 1.0 1 7/ 2/98 16:50 602/601 2641 E. Snith 1,4-Dichlorobenzene ND Uq/1 1.0 1.0 1 7/ 2/98 16:50 E. Snith 602/601 2641 Ethylbenzene KD uq/l 1.0 1.0 1 7/ 2/98 16:50 E. Snith 602 2641 Toluene KD ug/1 1.0 1.0 1 7/ 2/98 16:50 E. Snith 602 2641 1,p-Xylenes ND 1.0 ug/I 1.0 1 7/ 2/98 16:50 602 2641 E. Smith o-Xylene **RD** 1.0 ug/l 1.0 1 7/ 2/98 602 2641 16:50 E. Snith Bronodichloromethane dk uq/1 1.0 1.0 1 7/ 2/98 16:50 601 2641 E. Snith 3ronoforn YD. ug/l 1.0 1.0 1 7/ 2/98 16:50 E. Snith 601 2641 Bronomethane dk ug/l 1.0 1.0 1 7/ 2/98 16:50 601 2641 E. Snith Carbon tetrachloride DK 1.0 ug/1 1.0 1 7/ 2/98 16:50 E. Snith 601 2641 Chloroethane ND. ug/l 1.0 1.0 1 7/ 2/98 16:50 601 2641 E. Snith 2-Chloroethylvinylether DK 1.0 U4/1 1.0 1 7/ 2/98 16:50 E. Snith 601 2641



2960 Foster Creighton Dr. P. O. Box 40566 Nashville, TN 37204-0566 Phone 1-615-726-0177

# ANALYTICAL REPORT

Laboratory Number: 98-A75704

Sample ID: FF-MW-RS-1

Page 2

nalyte	Result	Units	Report Limit	Avan Linit	Dil Factor	Date	Tine	Analyst	Method	Ratch
Chloroforn	NO.	ug/l	1.0	1.0	1	7/ 2/98	16: 50	E. Smith	601	2641
bloronethane	MD	ug/l	1.0	1.0	1	7/ 2/98	16:50	E. Smith	601	2641
vibronochloromethane	מא	ug/l	1.0	1.0	1	7/ 2/98	16:50	E. Smith	601	2641
Ethylene Dibronide	ИĎ	ug/l	1.0	1.0	1	7/ 2/98	16:50	E. Smith	601	2641
inyl chloride	AD.	ug/1	1.0	1.0	1	7/ 2/98	16:50	E. Smith	601	2641
_ichlorodifluoromethane	ВĎ	ug/1	1.0	-1.0	i	7/ 2/98	16:50	E. Smith	601	2641
i,i-Dichloroethame	ЯD	ug/1	1.0	1.0	1	7/ 2/98	16:50	E. Smith	601	2641
1,2-Dichloroethane	KD OK	ug/1	1.0	1.0	- 1	7/ 2/98	16:50	E. Smith	601	2641
,1-Dichloroethese	XD.	ug/1	1.0	1.0	1	7/ 2/98	16:50	E. Smith	601	2641
cis-1,2-Dichloroethene	ЯĎ	ug/1	1.0	1.0	1	77 2/98	16:50	E. Smith	601	2641
trans-1,2-Dichloroethene	ND ON	ug/1	1.0	1.0	1	7/ 2/98	16:50	E. Smith	601	2641
,2-Dichloropropane	AD.	ug/1	1.0	1.0	1	77 2/98	16:50	E. Smith	601	2641
-cis-1,3-Dichloropropene	ИĎ	ug/1	1.0	1.0	1	7/ 2/98	16:50	E. Smith	601	2641
trans-1,3-Dichloropropene	КD	ug/1	1.0	1.0	1	7/ 2/98	16:50	E. Snith	601	2641
ethylene chloride	KD	ug/1	1.0	1.0	1	7/ 2/98	16:50	E. Smith	601	2641
.,i,2,2-Tetrachloroethane	מא	ug/I	1.0	1.0	1	7/ 2/98	16:50	E. Snith	601	2641
Tetrachloroethene	מא	ug/l	1.0	1.0	1	7/ 2/98	16:50	E. Snith	601	2641
1,1,1-Trichloroethane	NO	ug/1	1.0	1.0	1	7/ 2/98	16:50	E. Smith	601	2641
.,1,2-TrichLoroethane	ND.	ug/I	1.0	1.0	1	7/ 2/98	16:50	E. Smith	601	2641
Trichloroethene	D	ug/1	1.0	1.0	. 1	7/ 2/38	16: 50	E. Smith	681	2641
Trichlorofluoromethame	AD.	υg/1	1.0	1.0	1	7/ 2/98	16: 50	E. Smith	601	2641
KHETALSX										
Lead	KD	Hg/1	0.0030	0.0030	1	77 3798	10:10	R. Kelley	239.2	2815

#D = Not detected at the report limit.

Parameter	Mt/Vol Extracted	Extract Vol	Date	Analyst	Method
PAH's	900. нl	1.00 ml	7/ 2/98	Fitzwater	3510
Fla Pro	990. нl	2.0 ml	7/ 3/98	Schweikert	F0EP

Surrogate	% Recovery	Target Range
Fla Pro Surr., D-Terphenyl Fla Pro Surr., C-35 Hydrocarbon	123. 96.	82 142. 55 118.
PID Surr., a,a,a-trifluorotoluene	96. 99.	50 150.
Hall Surr., 2-chloropropane	86.	61 132.
Hall Surr., chloroprene	91.	64 130.





#### ANALYTICAL REPORT

Laboratory Number: 98-A75704

Sample ID: FF-MW-RS-1

Page 3

urrogate	% Recovery	Target Range	
all Surr., 1-chloro-3-fluorobenzene	88.	65 132.	
.AH Surrogate	52.	33 123.	

Report Approved By:

Maked D. River

Theodore J. Duello, Ph.D., Q.A. Officer Michael H. Dunn, M.S., Technical Director Danny B. Hale, M.S., Laboratory Director

Environmental Engl	Environmental Engineers and Scientists 1608 13th Avenue South															age:			
1608 13th Avenue Sou Birmingham, Alabama (205) 918-4000 (FAX)	ıth		58	96	105570 mass)						F		_		7	Preserve			
PROJECT NO.:					MATPORT FUEL	FACU		/cc	NTAINE	RS		/-	/	/	//	Cade:	A - 1	lone	
P.O. NO.:	- 1	LAB DESTIN			ECLAL ASSATS			/	7	/ /	_ o/		/ . /	/ /			B - I	H2 SO4	
	car.		SOIL WATER SOLD OTHER HON-AQUEOUS				E S	9/ 8/8	· / ¿	ş / .	g / g	./		D - 1	ici				
Lab Code — for Lab	rr. 98 Dalde 3	Time	S E E	a B S	Sample No./ Sample Location	SOIL WATER SOUD NON-A	/ ≥°	70/07	27.00	EE	EE	EE	E		/	REMA	RKS		
76312	930/16	8.47		F	F-MW-11	םם				X									
<i>f</i>						0000										<u> </u>			
		,				مممم										BHATE .		M	
						مممم										ANG T		(7)	
						0000					10.					20 C	,	100	
						مممم										ROZMENTA		N	
						مممم									j	Þ.			
						مممم									30				
						0000													
						مممم													
Relinquished by: (Sig	mature):			Time:	Received by: (Signature)	): Date:	îlme:	LAB	COMMI	ENTS									
M.C. MY	us		181	700			1700		40										
Relinquished by: (Sig	mat <del>ure</del> ).	: Date	-	Time:	Received by: (Signature)	): Date:	Πma:	REM REC	ARKS C	N SAME	PLE	SAMI	PLE SHI	PPING M	ETHOD	SAMPLE C	ATAO	NER TYPE	
10	nature):	: Date		Time:	Received for Laboratory	Dale:	Ilma:	1	le Intac	ot:	0	Han	d Delly	ary	P = Plaslic				
					by: (Signature)	-//	900	Chill	ed;				(specify or (spec			G = Glas		nber	
												-					بسرتنا و		

									VO.: 00001
Environmental Engineers and Scientists	CHA	N-OF-C	CUS	STODY	Page: 1 of 2				
1608 13th Avenue South					·	Tokes	PA KAG	5 / 4	
Birmingham, Alabama 35205 (205) 918-4000 (FAX) (205) 918-4050					/ =	A	/E/	EIB	Preserved (Code)
The state of the s	111		-	7	140	74/2	1 / A	or yes	/ Iced (yes/no)
PROJECT NO. 9770082 PROJECT NAME:	MAYBOT MUSTA/ Fuel	FARM		CONTAINERS	- 1x TX	T.	A STORY	137	Code: A - None B - HNO3
P.O. NO.: LAB DESTINATION		5135	/	' / /	M 3	3 3	8 2 3	12 m	C - H2504 D - NaOH
SAMPLER(*) NAME: De Wey TRA	my	, suo		/./	在了	V.8"	JM A	₹.%	E - HCI F -
		SOIL WATER SOLD OTHER NOW-AQUEDI	/ .	Yolum.		E E	8 F	\$	4
Lab Code – for Lab Yr Date Time g	Sample No./ Sample Location	SOIL WATER SOLD OTHER HON-ADUEDUS	/ & [;]	7 2 / F	4	/ E # /		7	REMARKS
75703 4/14881035	FF-55-RS1(50.7)		5	UN CON					
104 dzeka 1045	FF-MW-RSI (GW)	00000	6 2	11 Cem					
05 Wake 1125	IE-MW-10	مموم	6	IL GAT					
75706 druss 1210	FF-MW-10 FF-MW-11	םםשםם	1	12 000 P		~			No. 1974 - American de la companya d
/ /	7000-17	مومو	9	bel 600 C					
		مومو							
		0000							
		مومو							
		مووو							
		مممم							
Relinquished by: (Signature): Date:	Time:   Received by: (Signature):	Date: Ti	lma:	140,000,000					
Ja Jan Januar (176/158)	17.00			LAB COMMENTS	1				
Relinquished by: (Signature): Date:	Time: Received by: (Signature):	Date: 11	lma:						r
,			1	REMARKS ON S		SAMPL	E SHIPPING	METHOD	SAMPLE CONTAINER TYPE
	The Grant of the Late			Bottle Intact:		Hand	Delivery		P = Plastic
Relinquished by: (Signature): Date:	Time: Received for Laboratory by: (Signature):	Dale: Th	ma:	Preserved:		Air (s	pecify)	_	G = Glass
E	M B	93498 9.	200	Chilled: Other:			(specify)	0	GA = Glass Amber
ISTRIBUTION: WHITE COPY - Project File	YELLOW COPY - Lab copy	PINK COPY - Wor	rking File	9		100			F:\DWG\BLOCK\RCHAIN

	-   -		NO.: 00001														
Environmental Engineers an	_			CHA)	IN-OF-	CU	ST	OT	Y					F	age: 2 of 2		
1608 13th Avenue South				~~~~			~ ~			E	louis	as k	126				
Birmingham, Alabama 35205									•	/E		$\bot$	_/_		Preserved (Code)		
(205) 918-4000 (FAX) (205) 918-							7			144					/ lced (yes/no)		
PROJECT NO.: 9970082 PR	OJECT NAM	E: /	Ayp	post NAVSTA/Fux	el Farm		/ c	ONTAINE	RS	/ ,	/	/	/	/ /	Code: A - None B - HN03		
P.O. NO.: LA	B DESTINAT	ION:	5he	cialized ASSAY	5		/	/ /	/ /	2º /	/				C - H2504		
SAMPLER(1) NAME: Dewe	4 Tex	2160	,/		и	/	,	/ /	6	, /	/			/	D - NaOH E - HCI F -		
,																	
Lab Code — for Lab. Yr Date	Time (	G db G		Sample No./ Sample Location	SOIL WATER SOLD OTHER HOW-AQUEOU	/ %	25	3/3	E	\\\ \bar{E} \bar{\bar{\bar{\bar{\bar{\bar{\bar{	/EE	E	E		REMARKS		
75703 Clake	035		FF	55-RSI(Spil)	aàaa	1	12	GA	/								
\ , , , , , , , , , , , , , , , , , , ,	1045			55-R51(Eguss) -MW-RS1(Eguss) MW-10 MW-10	0000												
	1043	V	P	-111W-1031( Eging)		++-	11	GA	~								
05 dzyse	1175	V	FF	mw-10	- ckicc		10	68	1								
757.06 Ways	1210		FF	mw-11	OQOO	1	11	GA									
1-7	1				0000												
					٥٥٥٥	<del>                                     </del>											
		-		Marie		-									P		
<b>1</b>					مممم												
					0000										*		
					مممم												
		+				-											
		Ш			0000	<u> </u>											
Relinquished by: (Signature):	Date:	Ţ	lme:	Received by: (Signature):	Date:	Time:	Ш	B COMM	ENTS				- / u - 44m.				
An 1	11-11	110	7.	ý «													
Relinquished by: (Signature):	7/25/51 Dale:	4	790 Ime:	Received by: (Signature):	Date:	Time:	-						20-31 (6-21)				
monitoring of a day manage.	34.04	T		-/- (				MARKS (			SAMI	PLE SHI	PPING N	ETHOD	SAMPLE CONTAINER TYPE		
D. W	D=4=	-	Inc. a -	Received for Laboratory	Deter	Tlen	7	tle Inta	ct:		Han	d Delive	iry		P = Plastic		
Relinquished by: (Signature):	Date:	+	ime:	by: (Signature):	Date:	Ilma:	Preserved: Air (specify)					(apecify	)	☐ G = Glass			
	6/8/96	9:00	Other: Other (specify)														
													-	The second second			

Environmenta			liete			СНА	IN.	OF-		ST.	OT	V						Page:	-	
1608 13th Avenu	137 //	ilu Scielli	11515		1054		111	O1			OL	1	E	Tox	DA I	KAG				
Birmingham, Ala (205) 918-4000		4050			1054	02							/5	1/2	4 /E	1/ E	= / B	1	ved (Cade) yes/no)	
PROJECT NO.:95			ME: /	11. 4	111.1	+1511	· • •			7,	ONTAINE	DC.	140	\x	AF.	140	2/ 402		A - None	-
P.O. NO.:	10082	AR DESTIN	ATION:	IHYINI K	et NAVS	Traf Fuel	FAS	em		1	/	/ //	K XX	ST N		m	( ) T	Code.	B - HN03 C - H2SO4	
SAMPLER(a) HAME	7	- J	2 .	-)f	pecial	13th	55,03	£		/ /	/ /	LE.		X 17	1	P &	7 m		D - NaOH E - HCI	
SAMPLER(*) NAME: De Wey TRAMY													2 X Q	12	5 ) i		6. X		F -	
Lab Code — for l	abi Yr only Date	Time	Comp		Sample No./ Sample Loca		SOIL	SOLD C	/%	و الم	S. S.	E	EE	EE	E	E		REL	AARKS	
75702	Clruss	1035	L	FF	55-	RS 1(50.7.	) 0	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	5	40	GA GA					í				
1 04	alzeka	1045		FE	MW-1	RSI (CW)	) 🗆	(ØC)	6	250.2	CA GA	V			~	_				
105	6/2/58	1125	-	FÉ	=- Mw-	1//		baa	6	16	CAT			V	V	/				
757.06	42498	1710	V	FE	mw	-1)	<u> </u>	Ø O O	6	250l	POR			V	~					
	, ,						۵	000									1	4CL	Missin	8
							0	ممم								L	ite	- 8	Missin	
							a	000	<u> </u>					E		. P		DE-	PAH	1
	7							ممم							4	8.4	Ru	n FL	PRO,	•
						1	Q	000			,				W	e oh	auld	rec.	NICIK	
							۵	ممم							lan	F-1	1-2	11 for	PAH	
0.11	/s:l	Date		Time:	Received by:	: (Signature):		Dale:	Time:	<u> </u>			al.		J					_
Relinquished by:	(Signature):	Dais		111110.		( Lagrana)				LAB	COMME	ENTS	7/1/	198	/3	15	per	Sew	ey	
then 5	Jugge			700													Fr	app	, ~	
Relinquished by:	(Signature):	Date	:  -	Time:	Received by:	: (Signature):	· }-	Dala:	Time:		ARKS O		PLE	SAMI	PLE SHI	PPING 1	4ETHOD	SAMPLE	CONTAINER TYP	—
						Į.					EIVED E			┼						<u>.</u>
Relinquished by:	(Signature):	Date		Tlme:	Received for by: (Signal	r Laboratory		Dale:	Time:	7	erved:		, O	1	d Delly	-		P = Pic		
					MB		6	13485	9:00	Chil					(specify r (spec			G = Glo	ilasş Amber	
			L_		11 A		17			1				L						_

Environmental Engine					CH	AIN	IN-OF-CUSTODY									P	Page: 2 of 2.				
1608 13th Avenue South Birmingham, Alabama 35	205											E	Del	as A	AG		Preserved	(Code)			
(205) 918-4000 (FAX) (20											-1.	144	_				lced (yes/	no)			
PROJECT NO.:997008	2 PF	ROJECT NA	ME:	MA	yport NAUSTA/F	uel	FARM		/c	ONTAINE	RS	/_' /	,	/	/	/ /	Code: A	- None - HNO3			
P.O. NO.:	L	B DESTIN	ATION	5	beciatized ASS	25			/	//	/ /	20 \		′ /	/ /	/ /	C ·	- H2SO4 - NaOH			
SAMPLER(a) NAME: De	WO.	4 1	211	1			~ S	7	,	/ /		X /		/	/	/	Ē.	- HCI			
TITLE:		7 /~		<u> </u>		]	OTHE	/		Ę/.	/4	§ / . §	/ &	ş /	g /	§ /	*				
Lab Code — for Lab Yr.		Time	S G H	9 29	Sample No./ Sample Location		SOIL WATER SOUD OTHER NON-AQUEOUS UDUID	/%	25	7,70°	ES	S E S	E F	E	E E		REMARK	S			
75703 Ja	188	(035		F	F-55-R51(50il	(,)	adaa		12	GA	/										
) OH 4/2/	'	1045		)F	F-MW-RSIGE	(د	OBOO			COA	V							,			
1 05 0	/	1175		F	F-MW-RSI(Eg)	<i>p</i>	Okloo			GA											
757.06 4		1210		F	F-mw-11		OQOO	1	11	GA											
70	7	1-70	ľ				مممم		<del>  </del>												
		(a)					مممم									,					
				1	*		مممم														
				+			مممم														
			$\top$				مومو														
							0000														
																		-			
Relinquished by: (Signal	ture):	Dota	+	Time	a: Received by: (Signatur	a):	Date:	Rme:	M	B COMM	ENTS										
Dewy Turn		175/	57	179	)n (																
Relinquished by: Signa	ture):	Date	:	Time	a: Received by: (Signatur	w):	Date:	Time:	<del>-</del> -	11046			T								
•					l.					MARKS ( CEIVED I			SAMI	PLE SH	IPPING !	METHOD	THOD SAMPLE CONTAINER TYPE				
Bull-sulphed how /C/	tama li	Date	_	Time	e: Received for Laboratory		Date:	Ilma:	-	tia Inta	ct:		Han	d Delly	ary		P = Plasfic				
Relinquished by: (Signa	iura):	Date	+	11/11/0	by: (Signature):		Dura:	THUR.		served:			Alr	(specify	₍ )		G = Glass				
	MB MB						6/50/96	9:00					Other (specify)			۵	GA = Glass	Amber			